

NWB Annual Report

Year being reported: **2019**

License No: 1BR-MDR1721 Issued Date: July 31, 2017
 Expiry Date: July 30, 2021

Project Name: Former Iqaluit Metal Dump Remediation Project / Qikiqtanki

Licensee: Transport Canada

Mailing Address: 344 Edmonton Street, Winnipeg, Manitoba R3B 2L4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Dillon Consulting LTD./ Outcome Consultants Inc in joint venture (DOJV)

General Background Information on the Project (*optional):

During the 2019/2020 fiscal year completed a site investigation as per the long term monitoring plan (Arcadis, 2018) created following the 2017 remediation.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Long Term Monitoring Stations 1 through 7	
Water Quantity:	50/day	Quantity Allowable Domestic (cu.m)
	<1	Actual Quantity Used Domestic (cu.m)
	N/A	Quantity Allowable Drilling (cu.m)
	N/A	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

N/A

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

Revisions to the Spill Contingency Plan

N/A - not applicable

Additional Details:

Revisions to the Abandonment and Restoration Plan

N/A - not applicable

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Completed site investigation which included observation monitoring and extratction of surface water samples for each of the 7 long term monitoring stations for chemical analysis. Also, collected sediment samples from each of the stations as per the long term monitoring plan.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 31, 2019

Submitted/Prepared by:

John Cowan

Contact Information:

Tel: 204-791-2819

Fax:

email: john.cowan@tc.gc.ca