




Photograph LNH-1. Panoramic photo of the north slope. ____ ↑



Photograph LNH-2A. Facing east along crest from the centre of the north crest. ↑






Photograph LNH-2B. Facing west along the crest from the centre of the north crest. Some tire tracks visible but no damage or rutting. ↑



Photograph LNH-2C. Top of the landfill facing south from the centre of the north crest. ↑





Photograph LNH-3A. Facing north from the centre of the east crest. \uparrow



Photograph LNH-3B. Facing south from the centre of the east crest.





Photograph LNH-4. Facing northwest along the east slope. \spadesuit



Photograph LNH-5A. Facing west along the crest from the centre of the south crest.





Photograph LNH-5B. Facing north along the top of the landfill from the centre of the south crest. ↑



Photograph LNH-5C. Facing east along the crest from the centre of the south crest. ↑





Photograph LNH-6A. Facing north along the crest from the centre of the west crest.



Photograph LNH-6B. Facing south along the crest from the centre of the west crest.





Photograph LNH-7A. Facing northeast towards the west slope. ↑



Photograph LNH-7B. Facing southeast towards the west slope. ↑