



**Photograph VI-9: Gabion Walls Were Constructed to Form the Channel Through Which Water From the S1/S4 Beach Area Then Was Forced to Flow**



**Photograph VI-10: After the Geocomposite Clay Liner was Placed in Position, It was Wetted to Form a Sealed Channel**



**Photograph VI-11: A Black Liner Was Then Placed on Top of the GCL and Sealed Around the Filter Box. Sandbags Secured the Liner to the Contoured Channel**



**Photograph VI-12: Gabions Were Placed Across the Drainage Channel Above the Steep Slope Leading to the Barrier as an Additional Sediment Trap**





**Photograph VI-13: The Channel Above the Top Gabion Sediment Trap Was Lined With Cobbles To Trap More Sediment**



**Photograph VI-14: The S1/S4 Beach Barrier Nearing Completion**