





Photograph II-1: The 1994 Barrier Still in Place at the Start of the Season



Photograph II-2: The Same Area After PCB Excavation



Photograph II-3: Excavating Tier II Contaminated Soils at the S1/S4 Beach Area. The Green Areas May Still Contain CEPA Soils and the Top of the Disturbed Areas Tier II Soils. Both Were Too Dangerous to Excavate



Photograph II-4: Heavy Equipment Working at the S1/S4 Beach Area



Photograph II-5: Establishing the Grid in Between Excavating Tier II and Tier I Soils



Photograph II-6: Excavating Tier II Soils From a Platform Close to the Cliff