NWB Annual Report	Year being reported:	elect ▼ 2015
License No: 1BR-RLF		
	Expiry Date: Au	gust 16, 2020
Project N	me: Resolute Bay Land Treatment Units Ma	intenance Project
Licensee	Transport Canada - Programs Branch, Contar	minated Sites
Mailing A	dress: 344 Edmonton Street Winnipeg, MB R3C 0P6	
	ompany filing Annual Report (if different from Nam between the two entities, if applicable):	ne of Licensee please clarify
N/A		
General Background I	ormation on the Project (*optional):	
Resolute Fighter T were link LTU 1 is a berms. Z lighter hy FTA and A	ansport Canada constructed two Land Treatment ay Airport for the treatment of soils excavation for the soil of the soil	rom the Former Fire at the airport. The LTUs lene (OR RPE) liners. zones seperated by e zone 3 containted 00 m3 of soil from the
Licence Requirements with	the licensee must provide the following inform	nation in accodance
obtaining water; sewa	ter use and waste disposal activities, includin e and greywater management; drill waste man	
waste management.	Croundwater Menitoring Wells	
Water So Water Qu		Domestic (cu.m) rilling (cu.m)
	agement and/or Disposal lid Waste Disposal wage ill Waste eywater	

	Other:	
	Additional Details: No waste disposal activites were undertaken in 2015. Activites were limited to advancing test pits and soil sampling.	
A list of un	nauthorized discharges and a summary of follow-up actions taken.	
	Spill No.: N/A (as reported to the Spill Hot-line) Date of Spill: Date of Notification to an Inspector: Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)	
Revisions t	to the Spill Contingency Plan	
	Other: (see additional details)	
	Additional Details:	
Revisions 1	to the Abandonment and Restoration Plan	
	Other: (see additional details)	
	Additional Details:	
Progressiv	ve Reclamation Work Undertaken	
r regiocon	Additional Details (i.e., work completed and future works proposed)	
	Please see the attached Enviornmental Site assessment Report for the Resolute Bay Airport Land Treatment Units.	
Results of	the Monitoring Program including:	
		_
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) each location where sources of water are utilized;	of
	Not Applicable (N/A) ▼	

	The groundwater in all 6 monitoring wells was frozen at the time of the site investigation and no samples could be collected for analysis.
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) o each location where wastes associated with the licence are deposited;
	Not Applicable (N/A)
	Additional Details:
	No waste was deposited in 2015.
	Results of any additional sampling and/or analysis that was requested by an Inspect
	No additional sampling requested by an Inspector or the Board
	Additional Details: (date of request, analysis of results, data attached, etc)
	N/A All monitoring and sampling results are provided in the attached reports.
	er details on water use or waste disposal requested by the Board by November 1 of the ye
	No additional sampling requested by an Inspector or the Board
	Additional Details: (Attached or provided below)
·oor	consec or follow up actions on inspection/compliance reports
esh	No inspection and/or compliance report issued by INAC
	Additional Details: (Dates of Report, Follow-up by the Licensee)
	Additional Botalio. (Bates of Report, 1 offew up by the Electroco)
ada	itional comments or information for the Board to consider

Additional Details:

Date Submitted:
Submitted/Prepared by:
Contact Information:

March 29, 2016
Kelly Hunnie, Superintendent of Contaminated Sites,
Tel: 204-880-5128
Fax:
email: kelly.hunnie@tc.gc.ca