

Project Photographs

Long Term Monitoring, 2017
PIN-D, Ross Point, Nunavut



Photo: 13

Date:

August 2, 2017

Description:

Exposed debris, southeast of the NHL

Location:

Near Viewpoint 11

Direction Taken:

NW



Photo: 14

Date:

August 2, 2017

Description:

Exposed debris, southeast of the NHL

Location:

Near Viewpoint 11

Direction Taken:

N/A

Project Photographs

Long Term Monitoring, 2017
PIN-D, Ross Point, Nunavut



Photo: 15

Date:

August 2, 2017

Description:

View of burrow located southwest of the NHWL area.

Location:

SW of NHWL area (P54)

Direction Taken:

N/A



Photo: 16

Date:

August 2, 2017

Description:

Settlement (Feature D) in foreground, along NE side on top of NHWL.

Location:

Viewpoint 43 (Figure 2)

Direction Taken:

NW

Project Photographs

Long Term Monitoring, 2017
PIN-D, Ross Point, Nunavut



Photo: 17

Date:

August 2, 2017

Description:

View of access road, south of
the NHWL.

Location:

Viewpoint 47 (Figure 2)

Direction Taken:

N



Photo: 18

Date:

August 2, 2017

Description:

View of full jet fuel drum
located adjacent to the
runway area

Location:

Runway (P53)

Direction Taken:

N/A

Project Photographs

Long Term Monitoring, 2017
PIN-D, Ross Point, Nunavut




Photo: 19

Date:

August 2, 2017

Description:

View of contact information label attached to full jet fuel drum.

Location:

Runway (P53)

Direction Taken:

N/A



Photo: 20

Date:

August 2, 2017

Description:

View of the remnants of a campfire located along the access road to the NHWL area

Location:

Access Road (P59)

Direction Taken:

N/A