



**Photo 7 - Garage View - Looking West**



**Photo 8 - Vehicle Debris Area South of Garage - View West**





**Photo 9 - West Barrel Cache - View Southeast towards Station**



**Photo 10 - West Barrel Cache - View Northwest**





Photo 11 - POL Tanks - View Northwest



Photo 12 - Construction Camp Equipment and Debris





**Photo 13 - Dump A - View South - Debris Removed and Stockpiled in 1996/97**



**Photo 14 - Dump A - Stockpiled Debris and Wrangler Bags**





**Photo 15 - Dump B - View East on Bench below POL Tanks**



**Photo 16 - Dump B - View West - POL Tanks in Background**





Photo 17 - Equipment and Debris North of Dump B Area



Photo 18 - Domestic Refuse and Empty Barrels





Photo 19 - Quonset Building



Photo 20 - Asbestos Containing Materials inside Quonset Building