

Appendix II

Photographs

Site Photographs
CAM-3, Shepherd Bay




Photo 1: Aerial view of Station Area at CAM-3.




Photo 2: Station Area at CAM-3.



Photo 3: Sewage Outfall at Station Area.




Photo 4: Beach POL Area.



Photo 5: Existing Asbestos Landfill.



Photo 6: Northeast Landfill.

Site Photographs
CAM-3, Shepherd Bay



Photo 7: Northeast Landfill.



Photo 8: USAF Landfill.



Photo 9: USAF Landfill.




Photo 10: Beach Landfill.

Site Photographs
CAM-3, Shepherd Bay




Photo 11: Station Landfill.



Photo 12: Station Landfill.




Photo 13: Surface Staining at Pallet Line Area.



Photo 14: Debris at Borrow Area #7.



Photo 15: Barrels North of Abandoned Airstrip at Beach Area.



Photo 16: Barrels Southwest of Abandoned Airstrip at Beach Area.



Photo 17: DLCU Storage Area at Beach.



Photo 18: Debris at Beach Area.



Photo 19: Debris South of Beach POL.



Photo 20: Debris at Pallet Line.

Site Photographs
CAM-3, Shepherd Bay



Photo 21: Cold Storage Building at Station Area.



Photo 22: Communication Billboards and Feedhorns at Station Area.

Site Photographs
CAM-3, Shepherd Bay



Photo 23: Communication Dishes at Station Area.




Photo 24: Station POL Tank at Station Area.

Site Photographs
CAM-3, Shepherd Bay



Photo 25: HF Antenna at Station Area.



Photo 26: Airstrip POL Line.