



Waterproof
Paper

Name: ANDREW PASSALIS

Address: 511 PEPPERLOAF CRES.

WINNIPEG, MB

Phone: (204) 791.4938

Email: apassalis@mts.net

Project Description: 2012 KIRKMEET

LANDFILL MONITORING

CAM-1

CAM-3

DUKSBAK is a tear resistant, completely waterproof paper that is the perfect solution for field books and forms.

★ MADE IN CANADA ★

R.D. PENHALL LTD.

Unit 220-2088 No. 5 Road, Richmond, B.C. V6X 2T1

Phone: 604-244-7271 Fax: 604-244-8827

www.rdpenthal.com

(30)

CAM-3

AUGUST 21, 2012

OVERCAST 8°C, LT WINDS, LT FOG

BEACH LANDFILL

745 PAN NW-S FROM NW CORNER

746 V-NW ALONG N-SIDE

V-NW-NW. ALONG DRAINAGE CHANNEL

747 PAN NW-SW ACROSS TOP

748 DEPRESSION, SAME. V-SE

10' x 50-100' x 8'

C312-1 SE OF LF 3; WP 750

0-10' GRAY SAND, SOME GRAVEL

ORG. DAMP, W/

10-20' BRN " 20-45'

A-0-15 B-40-50

752 - PAN SW-SE FROM N END

SAMPLE C3

753 - PAN SW-ENE FROM N.E. SIDE

754 C312-3 WP 754

BRN/GRY SAND, W/ GRAY

Y@45 TR FINES

A-0-15 B-40-50

(33)

755 DEPRESSION ON CREST NW SIDE
15' x 10' x 15' + 40' x 60' x 15'

V WSW

756 LONG DEPRESSION ON COVER SAME

BUT 6-20' DEPT. V-S/NW

757 SECONDARY AREA UP TO 15'

758 BRN SSE - NE FROM W OF LF

759 C312-2 N OF LF

GRAY/BRN SAND, CS GR. W/TH

COVER, 40-40'

A-0-15 B-40-50 + BDI

760 - V. NWISE ON SIDE

761 V WNE / SSW ON MIN. EROSION

ON SIDE, DEP/WASH FINES

31-30' W, 3-5' WIDER

762 PAN. E-NW - SOUTH SIDE

763 V- WINE C DRAINAGE AROUND-

SE CORN OF LF, MIN. POND, 15' in

DEPN. AREAS - NO FLOW

764 - 5m L, 0.5m W, 10' UNEVEN

SURFACE AROUND TOE, GRAY SAND

V-N 1/4, MIN EROSION ON SLOPE

2x. 2' 10W. SEASONAL PONDING? FILL

⑤

[illegible]

(25)

STATION LANDFILL

LOBE A

771 - PAN SW-E CLOSER A-B

772 - V-S CLOSER A.

773 - V-SSE AWDH. E SIDE

774 - M-NOR MUST STAINING TOE

SOME -

775 - V-NWWD AT STAINING ON E TOE

776 - PAN. NE-W ACROSS TOP

777 - PAN E-N FROM S OF LOBE

MINER ON CENTER OF LOBE

LOBE B

778 PAN SE-NNE FROM SW OF LOBE

C312-5 WP-794

Q - BON LOBE SAND, WITH GRAVEL

SOME SILT, DAMP.

A-0-15 B-40-50.

795 PAN E-NW SOUTH OF LOBE

SAMPLE 26

796 END OF CRACK, MOSTLY INFILLED

EXTENDING NE UPSLOPE V-NE

797 END V-SW

11

(36)

79B - AREA OF DESIGNATION CRACKS, 1005
P. PUNSED. "AUGUST" 1M x 0.5M

2cm ↓ depr.

799/800/801 MIN. EROSION ON SLOPE
SLOPE. 2-3m L, 20-30cm W, 5 ↓
V-NE (SW) (TYP)

(11) NO CRACKS VISIBLE

802 ✓ V-E AROUND TOE / NW AROUND TOE

803 V-NNW AT MIN. EROSION
4m L x 10m W 3 ↓ 5 ↓

C312-G WP 804

0-1T BAN CLAY + SILT, TR
SAND + GRAVEL, MOIST
A- 0-15 B- 40-50

805 MIN. EROSION ON SLOPE
WASH FINESS, 4-5m L, 20-40cm

2-3 ↓ V-N/S

NO VISIBLE CRACKS AROUND S
TOE / SLOPE-AREA

806 V-N e MIN. EROSION 6m L, 20cm
2-3 ↓

(37)

807 TOE OF EROSION ALSO SMALL
DEPRESSION 30 x 30 x 7 ↓ V-N/S
EXT. TO TOE. 10m, 30 W, 5 ↓

808 V-S/N. e EROSION ON SLOPE - SAME
2x 2-5 ↓, 20-30cm W, 15L (18-20) (21/22)

809 PAN. ENE - NW FROM SE OF DORSE

810- 1- W/NE ALONG SIDE SLOPES

814 - C312-7
0- GRAY GRAVEL, SOME SAND
+ SILT, TR OR 4 TO 15. damp
A- 0-15 B- 40-50

812 V-NE e MIN. EROSION AROUND
SE TOE. FINESS, WASHING ONLY.

813 V-NW ALONG N. TOE.

814 PAN. NW-SW FROM CORN

815 MIN. EROSION / SETTLEMENT 3x
3-4m L, 20-50cm W, 5 ↓, V-SE

816 DEPRESSION. 2-3m x 10 ↓
V-NW

817 SMALLER DEPR. CREST 2x
SAME. V-SE

FIEL

NORTHEAST LANDFILL

LOBE D

VEZ ALONG NE + N TDE

848 V-S ALONG TDE

V-W CLIN DEPRESSION - SAME

849 V-S ALONG E SIDE

PAN N-S ACROSS TOP

C312-9 WP 847

BON SANDS + GRAVEL, DRY, W4

~~DEP~~ A-O-15 B-40-SD

SOME CONS.

850 V-NNE / W ALONG SIDES FROM

SE CORN

851 SMALL DEEP ON SLOPE L, 1ML,

20W x 5D V-E

852 V-N, ALONG W-SIDE

853 2x potholes 30x30 x W ↓

V-S

854 FROM DEEP TO SLOPE 11. BURSTLE

3 max. 0.5' PAN. S ↓ V-N

855 PAN. NE-W AT LOBE G.

SAMPLING

856 PAN. W-SE ACROSS TOP

(42)

LOBE F

C312-11

WP 8LTZ

BND CREST SAND, MED-CLST, WITHIN

GRAVEL DAMP

B-40-50

A-0-15

SAME

V-NIS

B-40-50

869 V-S E LOC DEPR. CREST.

60x30x10 ↓

870 V-S E DEPR ON SIDE / CREST SW

50-1m W, 10-15 ↓

871 V-S E LARGE DEPR. IN SCENT

AREA, SAME 30x10-50 ↓

DEEPER: NO IL

872 PAN. NW-SW C. DEPR.

874 PAN. N-W FROM SE OF W3C

873 V-W/N AROUND SIDES

875 V-SW E LIN DEPR. 2.5L, 30W.

10 ↓

876 V-N/ESE AROUND SIDES FROM

INSIDE CORN.

877 MIN. EROSION, 1cm, WASH-

FINES TOP-DE, 30-70 W-

V-E/W SAME

TOP ABOVE

878

(43)

879 LIN DEPR TOP SLOPE +

3m x 20m x 5 ↓ V-E

880 LIN. DEPR. V-SE. SAME

1.5L, 15W, 5 ↓

681 1m x 20 x 10 ↓

882 50x10x 5 ↓

883 V-S SIDE

884 V-SE / WSW SIDE

885 PAN SSW-E NE FROM NW CORN

886 DEPR ON SLOPE, V-S/E-15 ↓

TOP-DE 2mL, 0.7W, 10 ↓

C312-12 WP 887.

O - BRN SAND + GRAVEL WITH

DAMP, SOME CLST + BUDS

A-0-15 B-40-50

FIEL

(44)

AUGUST 22, 2012

8°C, MIST, CALM, OVERCAST

WP

LOBE A.

279 PANCI NE - NW FROM GRAVEL

PVE (SMALLER)

280 V - NNE / SW FROM SE COR.

281 V - SSW @ DEPR. ON E SIDE

282 1m x 1.5m x 10-30 ↓

283 V - 3 / NW FROM NE COR

284 UN-EVEN SETTLEMENT ALONG SLOPE

3 SE COR. 2x3m x 1m x 10 ↓

ON SLOPE

285 DEPR. ON CREST + 60x70x10 ↓

ALSO MIN EROSION TO N 1.5x1.5m x 3 ↓

286 DEPR. ON CRN 1m x 60x10 ↓ same

V - S / ENE AT EROSION ON CRN

2.5x1.5m x 5 ↓

287 ONE OF MANY EROS. ON SLOPE, V-E-

3m L, 20-30 W; 5-10 ↓ ALSO 287

288 C312-13

LT BAN SAND, med gr sand gravel

WITH

A.O-15 comp: B-40-50

(45)

LOBE B

289 C312-13

LT BAN SAND, SOME GRAVEL, TR

FINTS, MODIST - TR ORA, O-S

A-O-15

B-40-50

290 PAN E - NW CROSS TOP, SAMPLING

C 14. SW COR

291 WH. IMP. CRACK @ TOP SLOPE

SW 1-2cm W, V-S

292 PAN - E-N, FROM SW OF LOBE

293 PAN E - NW FROM MID S. SIDE

294 PAN N-SE FROM SE COR

295 V - NW AT DIST. AREA - SAME

296 V - W E MIN EROSION N. OF

297 SAME

298 V-E ALONG TR, MIN. EROS

1-2cm ↓ 30W, 4m L V-S

2x EROS. ON SLOPE - SAME

V - SE / NW, UP TO 5 ↓

299 V - ESE @ CH. EXT. FROM W TO E

OF LOBE, SUMMIT ON N-SIDE.

MIN EROS. TOP - TOE - 3-4 L, 30W

2-3 ↓ V-E

FIEL

(46)

300 V-E/W 3 we 3rd area
Eros. 3 x 40-1 m w s up to 10' ↓
TOR-TOE
301 LIN. DEPR. 4 m x 40 w x 10' v-s.
303 PAN S-E 0 WSE (NW slope)

LOBE C
304 PAN. E-N FROM SW OF LOBE
305 C312-15
RAW (CLAY) SAND, W/ GRAVEL,
SOME SILT, 2' C35.
A-0-15 B-40-50.

LOBE G
306 C312-16 ATTACHED TO
DRAIN CH. W. OF LOBE.
AT BASEN SILT SAND, SOME
GRAVEL, W/ GRAVEL, TRASH
A-0-15 B-40-50 A03

308 C312-17 HEAD OF DR.
CH.
V-E/W 0-BEN (CLAY) TAMP, MED-GS
GR. SOME GRAVEL, DAMP
A-0-15 B-40-50

(47)

309 C312-18 NW OF LOBE.
BEN SAND (W/ GRAVEL) ROCK
SOME SILT, DAMP, TAMP, TO 10'
A-0-15 B-40-50.

LOBE H
310 V-NNE ALONG E SIDE.
311 MIN. EROSION NE (RMR. V-NNE)
ELEV. 5 FT. 2 m V-SLOPE 50W, 5' ↓
LEADING TO DR. (FINE WASH) ON
SLOPE: 2 m L, 1 m W, 2' ↓
312 V-SSE/W ALONG SIDES FROM NE
CNR.
313 2 DEPR. ON CREST + SAME.
V-SSE 15-2 m L, 20 m 10' ↓
314 V-SSE E N END
315 V-SSE ALONG W SIDE
316 ROCKY ROTHOLE 25 x 20 x 10' ↓ V-E

FIELD

NON-HAZARDOUS WASTE LANDFILL

MUD-1. WP 317
SLIP-0.40 dia = 1 1/2"
1.94 bottom 2.00
INSUFFICIENT VOLUME.
TP - 3.5 m/s
0- BEN SAND, SOME GRAVEL, M
CS CR, DAMP.
A- 0-15 15-40-50
318 PAN NW-S. FRONT ROAD
319 V. SW/NW FROM NIE TOE
320/321 V-SW E N FACE
322 V. SE/SW E NW TOE
323 PAN S-W FROM NW OF LF
324/325 V-SW E NW FACE 15"
326 V-NE/SE AT SW TOE
327/328 V. NE E SOUTH FACE
329 V-NW/NE FROM SE TOE
330/331 V-NW E E FACE
332 PAN E-NW ACROSS TOP
333 DEPR. BELOW CREST V-NW/SE
2m x 1m x 104

Coarse veg on S face.

334 PAN SE-N ACROSS TOP
335 EROD. DEPR. ABOVE CREST.
6m x 40 x 5-10 V. NW/SE.
336 MUD EROS. TOP TOE V-NW.
15W, 2W
337 LOC-DEPR BELOW CREST 20x30x
104 V-NE
338 V-NW, MIN EROSION. TOP-1/2
SCOPE, WASH FINES 2-5 & 20W.
339 PAN SW-E ACROSS TOP. NW/CRN
340 LOC DEPR. 4m below crest 40x20x
5-7W
341 MIN EROSION. TOP-5m down.
2x30W. 2-3W V-SE
342 CB 2-3W 3m NE of well
0- BEN SAND WITH GRAVEL, DAMP
W. CR TR. CR 15-20
A- 0-15 15-40-50

50

MW-3W

SUP 0.40

2 day

bot. 1.79 fog

MW-2W

WP 3.44

SUP 0.34

2 day

bot. 1.72 fog

Am 5.6 MW

0- LT BEN. SILTY SAND

SOME GRAVEL DAMM. TRAPS

TO 10

A-0.15

B-40-50

B.D.4

345/46/47 V-SE ACROSS TOP

348 V-ORSE EXC. DEBRIS - SAME

349/50/51 V-NW ACROSS TOP

(3 LOCATIONS)

51

TIER II DISPOSAL FACILITY

SUP 55

2 day

MW-4

bot. - 2.24 fog

TO 4m S. BLUWELL

0- LT BRN. GRAVEL WITH

SAND & CLBS, DAMP W. 1/2

A-0.15 B-40-50

BL

352 PAN

SEE - E FROM NW/RODA

353 V-SIE FROM NW TDE

354/55/56 V-E & W SLOPE

357 V-E 1 N & SW TDE

358 V-E C E POS. ON W FACE

20-40 W TOP-TDE, 3-5 V-

359 START OF CRACK, V-S

~ 7m UP FROM TDE + SLOPE

PAN GRAVEL CRACKS 50 APART

R. IN FILLED 1-2 cm W.

... MERGES TO 1 CRACK 1/2 WAY

EXT. TO SW CRACK

WP 361

MW-7

4m ENE

0-1 ft ben. Silty sand & gravel

damp

B.D.5 A-0.15

B-40-50

FIEL

52

362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466	467	468	469	470	471	472	473	474	475	476	477	478	479	480	481	482	483	484	485	486	487	488	489	490	491	492	493	494	495	496	497	498	499	500	501	502	503	504	505	506	507	508	509	510	511	512	513	514	515	516	517	518	519	520	521	522	523	524	525	526	527	528	529	530	531	532	533	534	535	536	537	538	539	540	541	542	543	544	545	546	547	548	549	550	551	552	553	554	555	556	557	558	559	560	561	562	563	564	565	566	567	568	569	570	571	572	573	574	575	576	577	578	579	580	581	582	583	584	585	586	587	588	589	590	591	592	593	594	595	596	597	598	599	600	601	602	603	604	605	606	607	608	609	610	611	612	613	614	615	616	617	618	619	620	621	622	623	624	625	626	627	628	629	630	631	632	633	634	635	636	637	638	639	640	641	642	643	644	645	646	647	648	649	650	651	652	653	654	655	656	657	658	659	660	661	662	663	664	665	666	667	668	669	670	671	672	673	674	675	676	677	678	679	680	681	682	683	684	685	686	687	688	689	690	691	692	693	694	695	696	697	698	699	700	701	702	703	704	705	706	707	708	709	710	711	712	713	714	715	716	717	718	719	720	721	722	723	724	725	726	727	728	729	730	731	732	733	734	735	736	737	738	739	740	741	742	743	744	745	746	747	748	749	750	751	752	753	754	755	756	757	758	759	760	761	762	763	764	765	766	767	768	769	770	771	772	773	774	775	776	777	778	779	780	781	782	783	784	785	786	787	788	789	790	791	792	793	794	795	796	797	798	799	800	801	802	803	804	805	806	807	808	809	810	811	812	813	814	815	816	817	818	819	820	821	822	823	824	825	826	827	828	829	830	831	832	833	834	835	836	837	838	839	840	841	842	843	844	845	846	847	848	849	850	851	852	853	854	855	856	857	858	859	860	861	862	863	864	865	866	867	868	869
-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----

③

276	TOP CRACK	~ 3m up + EXT TO
	WEST	v - WE 376
377	C312 - 602	2m WNW
	0 - dk brn silt w/ blk org	
	20 - gray sand + gravel, med,	
	some fines	70-45
	A - 0-15	B - 40-50
	SUP 058	70,928
	boat: L38	
	pH	8.60 / 8.30 / 8.17
	COND	201 / 204 / 208
	Temp	30 / 28 / 22
	Turb	42 / 54 / 92
	"C312 - 5 W"	"UP 377
	SUP 072	70.020
	Bottom	1845
	* heaved, 3.5m SSE,	
	1 + ter brn silt, w/ sand + gravel	
	A - 0-15	B - 40-50
	pH	8.37 / 8.06 / 7.99
	COND	515 / 546 / 568

Temp: 3.6 | 3.7 / 3.2
Tues - 09 / 112 / 131

FIELD

	PAN NE-SW ACROSS TOP - SE CNR
	NOTE SEVERAL SMALL AREAS OF
	PUMPED IL ON COVER / 3 days @ 100
391	PAN NW/SE ACROSS TOP @ NE CN
392	DEPR ON MID SLOPE. 40x30x10↓
393	V. NW @ DEPR. ON COVER - SAME
394	PAN SW-NE @ NW TOP CNR
395	V-S @ SURFACE DEPR. ABOVE CREST
	5m x 0.6 x 5↓
396	LOC. DEPR. @ CREST. 40x40x5. V-N
397	V-W @ EROSION TOP-TOE

376	-SW CNR - V-E @ SUMMERED
	PROPS. NOTE IS @ DEPR. IN RUTS -
377	MIDDLE OF AREA. 6m W.
	CONCRETE 2-3m UP, 5-7m UP.
	SUCCESSIVE: V-NE
380	V-E V-TO 4 // CRACKS UP TO
	3-4cm W.
381	CRACK. 6cm W. OVER 18" ↓
	V-E
382	V-W @ CRACKS → 3-5m UP.
383	V-N @ EROSION TOP-TOE.
	V-S @ 5m ↓
384	V-S @
385	PAN SE - NW @ SW CNR TOP
386	SMALL DEPR. 2m BELOW VT 10↓
	V-N.
387	V-S @ SMALL DEPR. 0.5m below
	crest 15↓
387	V-E @ DEPR. ON CREST 0.5L 20w 10↓
388	V-S @ 2x EROSION 30w, TOP-TOE.
	VT TO 5↓
389	V. SE @ DEPR. BELOW CREST
390	V-N @ " " MID SLOPE ON
	SE CNR

(30)

USAF LANDFILL

308 MW-12 LOCK MISSISSAUGA

SLUP 037 2 day

BOH 1395

4m W of MW-

0-dk brn sand, some black clay,

damp

20 brn sand, med gr. p.g. damp

A-0-15 B-40-50

399 PAN ESE-SW

400 01/02 V-SE @ NW FACE

403 PAN SE-NNE FROM ROAD-

404 05/06 107 V-NNE @ S FACE

408 CB12-13W-

SLUP 34 B 0.530

BOH 1765-

AMS. 9m

BIN/CORRY SAND, TR. GRAVEL

M-ES GR. 7 EOB, NEAR 00-15

A-0-15 B-40-50

PH 8-30/8-18/8-16

COND 3.63/4.21/4.40

Temp 2.8/2.7/2.7

T. 1.22 21/42/146.

(57)

409/410 V-NNE @ S FACE-

411 PAN NE-NW @ SE FACE

412 V-N @ SE FACE

ALSO MW-14

CB12-14W. 4m S of MW-

SLUP 0.48 B 0.691

bottom 1.85

0-dk brn blk sand w org

damp.

15 grey silty sand + gravel, damp

W.G. 1E 45.

A-0-15 B-40-50

PH 8.57/8.42/8.40

COND 2.32/2.03/2.01

Temp 2.6/2.6

TURB 121/146/151

413 V-NW @ S END-

414 PAN NW-SW @ S END-

415 11/17 V-SW @ N. FACE

418 - MW-15.

FIEL

RAIN.	
C312-15W	0.605
5100 = 0.51	1.71
0-15 dk gray sand, fg p g.	
15 - gray sand, w gravel, v e 40	
15 - 0-15	B-40-50 B-50
PH	5.46 / 9.06 / 8.97
COND	410 ms / 370 / 391
TEMP	49 / 37 / 25
TURB	89 / 112 / 102
419 / 420 V-	SW e N. FACE.
421 V-	SE ALONG N. TDE
422 PAN	SW-SE FROM ROAD.
NWS LANDFILL	
423 PAN	SE - NE FROM RD
424 TBM / BMLG	
425 126 / 27	V-NE e S. FACE
428	V-NW e SE END.
429	V-WNW
430 130 / 32	V-SW e N. FACE.
433 PAN	SW-SE FROM ROAD
434	V-SE DOWN CL

USAF LANDFILL

435	V-SE AT PONDING E TDE
436	V-SW AT VEHICLE RUTS E TDE 6 x 20W x 23W x 5H
437	IL, MIN STAIN E TDE, V-E. SAN
438	M.B STAIN - INSIDE TDE 4ML.
888	30W, BACT SKELETON, V-SE IRON ST. IN PONDING E TDE V-NE VER BELOW V-T-SAME
NWS LANDFILL	
889	C312-21 0 - BRN SAND + GRAVEL W.C. SAND CRUS. CAMP A-0-15 B-40-50
890	C312-20 0 - BRN SAND M-C gr, some gravel, H-crags 0-10, camp A-0-15 B-40-50

(60)

0911 C312-1a: VERGAD.
CROW SAND, C312-1a, P. 9,
dome to ground
A-0-15 15-40-50
MANUAL READING OF TIE 11
3 USAF LF: RAINIER TOP
WENT TO CONTACT LATER.
RETRIEVE UNITS TO MOD TRAIN
TO CHANGE RATHER THAN
- LOAD

(61)

AUGUST 23, 2012

FOR: OVERCAST, SE @ 1520 km/h

REINSTATE DATA LOGS @ USAF LF

900 - LOC DEPRESSION ON SLOPE 4m FROM
TOE N.W. 40x50x10
NO DEBRIS VISIBLE

901 - DEPRESSION 6m FROM TOE
50x50x7m V.W.

902 - IN NW POINTING ABOUT TOE

903 - EROSION TOP TOE V-WNW

2.3m W. 2.5m E. PINEBETTER

20-40W AT CREST SPREADING

WENT DOWN SLOPE,

904 V-ESSE SAME DEPRESSION TO

S. SIDE V-SW

PAN N-SW ACROSS TOP

ALL PREV. CRACKS IMPROVED - NO EVID.

905 3m L CRACK 4m UP TOWARDS TOE

1-3cm W. INSIDE DIR V-SSE

906 4x2 - BURST DEBR. 6m UP FROM TOE

x15 V-SW E-W DIR

SPARSE VEZ

LESSON 12 FIELD

63

REINSTATE DATA VOLUNTEERS

[illegible]

2E L A = L O B E C

[illegible]

U
E
J
W
S
Z
Q
A
Z

7. Поттоилс 60x20

2-5-10x

205 11 5 3 5

2
5
3

ack 45° (SW) mid.

$\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$

[illegible]

FD 926-1E2D : V-EN

3
2
4
3
0
1
10
2
10
1
3
5
2

- E/S: AUNT SIDES

[illegible]

2	1
3	2
4	3
5	4
6	5
7	6
8	7
9	8
10	9
11	10
12	11
13	12
14	13
15	14
16	15
17	16
18	17
19	18
20	19
21	20
22	21
23	22
24	23
25	24
26	25
27	26
28	27
29	28
30	29
31	30
32	31
33	32
34	33
35	34
36	35
37	36
38	37
39	38
40	39
41	40
42	41
43	42
44	43
45	44
46	45
47	46
48	47
49	48
50	49
51	50
52	51
53	52
54	53
55	54
56	55
57	56
58	57
59	58
60	59
61	60
62	61
63	62
64	63
65	64
66	65
67	66
68	67
69	68
70	69
71	70
72	71
73	72
74	73
75	74
76	75
77	76
78	77
79	78
80	79
81	80
82	81
83	82
84	83
85	84
86	85
87	86
88	87
89	88
90	89
91	90
92	91
93	92
94	93
95	94
96	95
97	96
98	97
99	98
100	99

2021-2022

2x Vortices on sheet

$$30 \times 30 \times 10 \times 10 \times 10 \times 10$$

V. S. e. CRACK - A.T. CRES

1-2 discount: avoid cash

↑
K
m: Ds120 =

[illegible][illegible]

7x 500000

ALSO CHECK LN - 3

Also check $\ln - w$ slope FIEL

(64)

Settlement on slope down graded at

Cracks 8m L 2m W, 15V-20h

934 N. EROSION ON SLOPE 4m L, 30m W

S-104 V-E

935 V-N FROM SW CORNER

POTHOLE @ CREST: 30x30x15 ↓

936 MIN. EROS. V-N. 3m L x 10m x 5 ↓

LOBE 937

937 PAN. NEC-ESE FROM SE CORNER

938 MIN. DEPR. 40x40x5 ↓ SOME FINES

WASH DOWN GRAD. 15m L.

939 V-W EROS. ON SURFACE 20m L

30-100 W, 1-3 ↓ FINES WASH.

940 SAND L. STAIN - SAME → 940

942 V. 100W / N FROM SE CORNER

943 V-S AROUND E SIDE FROM NE

CRACK

944 V. N. E. 1-2 CRACKS, P. INFILLED

1-2 cm W, 1m L, TOE AROUND SURFACE

945 V-S C. INFILLED CRACKS

945 V-S C. EROS. ON SLOPE. 3m L x

1-30-40 W x 2-3 ↓

(65)

946 END OF INFILLED CRACK V-E NNE

TOE CRACKS 4x 3-6m L, 10m W

5-10 ↓ V-W

947 V-E / N FROM INSIDE CRACK

948 PAN W-SE FROM N END

V-W AROUND N-SLOPE

949 V-S AROUND W SIDE

950 POTHOLE 50x25x15 ↓

951 V-SE FROM NW OF LOBE

952 START OF 2 CRACKS FROM UP

FROM TOE. 2 SLOPE, V-S. 1-3 cm W

953 V-N. NO CRACKS END

954 V-S. WE. SETTLING IN TON SURFACE

2.5 L x 15 W x 10 ↓

955 NO EVID. OF CRACK, V-N. W.

956 V-S. 2x CRACKS EXT. FROM TOE

UP 2m ~ 8m. 1-2 cm W. V-N

→ TO 957 DISCONT BREAK V-N.

UP TO 3 cm W.

958 V-W. NW CRACK. 4m L x 2-3 cm

W. SESE

959 CONCAVE CRACKS 2-3 FROM TOE

UP 4m. V-SE 1-3 cm W

UP. 6-7m from toe @ 960

END 961 V-N NW

ALSO VIEW AT FIELD

(67)

530 DEPART CAM-3 ON TWIN
TO CAMBRIDGE BAY

JAY VICTOR EVALK

FIEL

962	V-W(N	AT INSIDE TOE
963	V-W(SE	E LARGE CRACK. 5m L, 2-8cm W
964	PAN.	S-NE ACROSS WOSE
965	V-SE	AWAY S FACE.
	SL	TO S.
966	START OF	CRACK./SUMP.
	SL	TO S. V-SE L-967.
	UP TO	15cm W. 35cm L
968	PONDISE	ON COVER 0.3x7m L ^{x2}
969	START OF	2nd concrete crack toe up 5m from toe. - track.
	V-E	1-2cm W, → 970.
	then curves to toe.	V-NW & 971
	V-NE	
972	V-W C S	END - NOTE 3 E TOE
	W HOLE	
973	V-S	E MIN DEPT. 3m UP 0.4x15x10L
891-293		4-2WA
2-10A		5-7WA
3-16B		6-15WA