NWB Annual Report		Year being reported: 2013 ▼
License No:	1BW-DUV1214	Issued Date: July 17, 2012 Expiry Date: July 16, 2014
	Project Name:	
	Licensee:	Fisheries & Oceans Canada (DFO), Small Craft Harbours Branch, Central & Arctic Region
	Mailing Addre	501 University Cresent Winnipeg , Manitoba R3T 2N6
		pany filing Annual Report (if different from Name of Licensee please clarify een the two entities, if applicable):
General Bac	kground Inforn	nation on the Project (*optional):
	to support the equipment pa	er Crossing was installed in November 2009. The crossing is required e construction of the Pangnirtung Small Craft Harbour to enable heavy ssage between the harbour and the municipal quarry. Construction was completed in September 2013.
Licence Req with	uirements: the	licensee must provide the following information in accodance  Item 1
	ater; sewage an	use and waste disposal activities, including, but not limited to: methods of ad greywater management; drill waste management; solid and hazardous
	Water Source( Water Quantity	
		ous

A list of una	uthorized disc <u>harges and a summ</u> ary of follow-up actions taken.
	Spill No.: None Reported (as reported to the Spill Hot-line)
	Date of Spill:
	Date of Notification to an Inspector:
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
Davisions to	the Spill Contingency Plan
Kevisions it	
	SCP submitted and approved - no revision required or proposed
	Additional Details:
	An updated Spill Contingency Plan dated September 15, 2012, was submitted to
	NWB on September 24, 2012.
	NWB on September 24, 2012.
Revisions to	the Abandonment and Restoration Plan
	No Abandonment and Restoration (AR) Plan submitted or approved
	Additional Details:
	An Abandonment and Restoration Plan was submitted on January 17, 2013. Any
	revisions to the plan, should they be required, will be addressed in the 2013 NWB
	Annual Report.
<b>Progressive</b>	Reclamation Work Undertaken
	Additional Details (i.e., work completed and future works proposed)
	N/A
<b>.</b>	
Results of the	ne Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each
	location where sources of water are utilized;
	Details described below
	Additional Details:
	DUV-1 (Duval River Crossing ) 69° 9'2.87" N; 65° 41' 30.01" W
	DUV-2 (Drainage Redirection) 66° 8' 40.00" N; 65° 42' 55.00" W
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each
	location where wastes associated with the licence are deposited;
	Not Applicable (N/A)
	The state of the s
	Additional Details:

## Results of any additional sampling and/or analysis that was requested by an Inspector • No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported. No additional sampling requested by an Inspector or the Board • Additional Details: (Attached or provided below) Any responses or follow-up actions on inspection/compliance reports No inspection and/or compliance report issued by INAC Additional Details: (Dates of Report, Follow-up by the Licensee) Any additional comments or information for the Board to consider **Date Submitted:** April 16, 2014 Submitted/Prepared by: Adele Butcher (DFO) **Contact Information:** Tel: (204) 984-3962 Fax: (204) 983-7166 email: adele.butcher@dfo-mpo.gc.ca