

☒ Original
☐ Follow-Up Report

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected			
Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen			Water Management Structures			Storage		
Flow Measure. Device			Culverts / Bridges			Spills		
Source:	A	1	Drainage			Spill Plan		
Water Use:	A	4	Erosion / Sediment					
Recirculation (y /n)			Mitigation Measures			Administrative		
			Reclamation Activities			Records	A	5
			Materials Storage			Reports		
Waste Disposal			Signage			Plans		
Waste Water						Notifications		
Solid Waste			Monitoring			Other		
Hazardous Waste			Sample Collection / Analysis			Equipment Used	A	2
						Construction	A	3
*The number in the comments field will correspond with specific comments provided below.								
Samples taken by Inspector:			Location(s):					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No								

Canada



Licensee or Representative	Inspector's Name
	Baba Pedersen
Signature	Signature
	Signed Original on File
Date	Date
	2020 November 20

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

cc. CIRNAC, Manager Field Operations, Iqaluit, justin.hack@canada.ca

Nunavut Water Board, Manager of Licensing, Gjoa Haven, licensing@nwb-oen.ca

PHOTO LOG

Date	Camera	Inspector	Authorization
2020 August 14	Sony DSC-HX50V	Baba Pedersen	1WLC-KFH1920
Photo Log # DSC06345			
Photo 1			
			
Description: The Location on the Kugajuk River where Kudlik Construction retrieved their Water from with their Water Truck			
Photo Log # DSC06353			
Photo 2			
			
Description: The Water Truck used to Haul Water from the Kugajuk River			



Photo Log # DSC06349

Photo 3



Description: Construction of the Fire Hall – View 1

Photo Log # DSC06350

Photo 4




Description: Construction of the Fire Hall – View 2



Photo Log # DSC06351


Photo 5



Description: Water Usage Information provided by Kudlik Construction

Photo Log # DSC06352

Photo 6



Description: A copy of NWB Approval # 1WLC-KFH1920 Letter & Conditions on Display in the Kudlik Construction Job Shack – Thank you