604 696 3401

NWB2(LAU0507)

01-19-2007

NWB Annual Report	Year being reported: 2006 ▼	
License No: NWB2LAU0507 -		
	Expiry Date: March 31, 2007	
Project Name:	Laughland Lake Project]
Licensee: Ke	nnecott Canada Exploration Inc	
Mailing Address	354 - 200 Granville Street Vancouver, BC V6C 1S4	
	ny filing Annual Report (if different from Name of Licensee please clarify n the two entities, if applicable):	-
General Background Information	tion on the Project (*optional):	
(Lat 66° 9' 54"N L of surface till sam	nt exploration 5 tent camp was established near Snow Bunting Lake ong -94° 25' 9"W, WGS84) in May 2005. Exploration work consisted pling and ground geophysical surveys. No drilling was undertaken.	
with	Item 2	
A STREET, STRE	Control of the Contro	leded Hele
Water Source(s):	Snow Bunting Lake	
Water Quantity:	5 Quantity Allowable Domestic (cu.m) 0 Actual Quantity Used Domestic (cu.m)	navut Water Board
✓ Solid Waste	ent and/or Disposal Disposal	AN 1 9 2007
✓ Sewage ☐ Drill Waste ✓ Greywater ☐ Hazardous ☐ Other:	Pub	olic Registry
Additional Details:		
the property, and t	amp remained closed for all of 2006. No work was conducted on the camp is still winterized from the end of the 2005 field season. harge occurred during 2006.	

604 696 3401

NWB2(LAU0507)

	unauthorized discharges and a summary of follow-up actions taken. Spill No: None (as reported to the Spill Hot-line)
	Date of Spill:
	Date of Notification to an Inspector: Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
	Additional Details. (Impacts to water, mitigation measures, shorthong term monitoring, etc)
wision	s to the Spill Contingency Plan
	SCP submitted and approved - no revision required or proposed
	Additional Details:
	Required addendums submitted May 4, 2005.
	E to the Abandoniment and By Manual Plan
	AR plan submitted and approved - no revision required or proposed
	Additional Details:
	Required addendums submitted May 4, 2005.
ogress	ive Regismation Work Unidertaken
	Additional Details (i.e., work completed and future works proposed) None to date.
	Additional Details (i.e., work completed and future works proposed)
	Additional Details (i.e., work completed and future works proposed)
	Additional Details (i.e., work completed and future works proposed)
	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program including:
idulta i	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program Including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
ssulta e	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program including:
urutta i	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below
esulte i	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below Additional Details:
	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below
	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below Additional Details:
SELUTION	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below Additional Details:
esulte i	Additional Details (i.e., work completed and future works proposed) None to date. The Monitoring Program including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below Additional Details: Lat 66° 9' 50"N Long -94° 25' 14"W, WGS84 The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
esulta i	Additional Details (i.e., work completed and future works proposed) None to date. The Blonkoring Program including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below Additional Details: Lat 66° 9' 50"N Long -94° 25' 14"W, WGS84
e elte e	Additional Details (i.e., work completed and future works proposed) None to date. If the Monitoring Program Including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below Additional Details: Lat 66° 9' 50"N Long -94° 25' 14"W, WGS84 The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited; Details described below
	Additional Details (i.e., work completed and future works proposed) None to date. The Blantoning Program including: The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized; Details described below Additional Details: Lat 66° 9' 50"N Long -94° 25' 14"W, WGS84 The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

NWB2(LAU0507)

	Results of a	ny additio	onal samp	oling and	or analys	sis that v	was req	uested t	y an Ins	spector
	No additional sa	mpling requ	ested by an	Inspector or	the Board				_	
[Additional De	etails: (dat	e of reque	st, analys	is of resul	lts, data a	attached	, etc)	"	1
	:									
		rute pr		sacelites		y stor Se	ant by	(eyanıb	er (1 65 d	NECES
	No additional sa	mpling requ	ested by an	Inspector or	the Board					
	Additional De	etails: (Atta	ached or p	rovided b	elow)]
	es ar fulla de						gerk kaluar			
indrica di Amerikana di Amerikan Amerikana di Amerikana di Amerika	No inspection ar								\	
r	Additional De	tails: (Dat	tes of Rep	ort, Follov	v-up by th	e License	ee)			•
The state of the s	Plans are bei	Account to the second second	to perman				nove all	facilities		
							•			
L							ing grafik kalan Sanggaran Tan Sanggaran			
Date Submitte			19, 2006	1				<u>1</u>		
Submitted/Pr Contact Infor		-	604 696 34							
		_	604 696 34 Den pezaro		.com					
		L-								