

NWB Annual Report

Year being reported: 2012 ▼

License No: 2BE-MSX0712 Issued Date: May 16, 2007
 Expiry Date: December 31, 2012

Project Name: Muskox Project

Licensee: Silvermet Inc.

Mailing Address: 8 King Street East, Suite 1700
 Toronto ON M5C 1B5

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Activity in 2012 was limited to cleaning up the camp site and a fuel cache

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Silvermet camp and drilling locations - no water use in 2010		
Water Quantity:	included below	Quantity Allowable Domestic (cu.m)	
	none	Actual Quantity Used Domestic (cu.m)	
	18 cu m/day	Quantity Allowable Drilling (cu.m)	
	none	Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

All waste at camp site was removed by Kikiak Contracting and taken to their yard in Kugluktuk

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

▼

Additional Details:

Revisions to the Abandonment and Restoration Plan

▼

Additional Details:

A plan was submitted on April 9, 2012 to deal with final clean up requirements as noted in prior inspection reports.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

On April 2, 2012, Kikiak Contracting removed the 18 barrel fuel cache located at N 66 degrees 59' 17" & W 114 degrees 54' 13" and took these to their yard in Kugluktuk. Kikiak Contracting returned to the camp site on August 15, 2012 to complete the remaining clean up as per the Plan. They completed the following:

- removal of all infrastructure materials, fuel caches, drums, barrels, dock, water pumps and lines and any other materials from camp site (N 66 degrees 59.2 & W 114 degrees 54')
- grey water sumps and sewage pits were back-filled to natural land contours at the camp site
- latrine pits were treated with lime and covered with native materials at the camp site
- other surface disturbances were returned to natural conditions.

Because of weather conditions, Kikiak Contracting was not able to get to the drill laydown area (N 66 degrees 45' 11.5" and W 115 degrees 11' 29.8"), nor were they able to inspect each of the drill locations. This was deferred until the subsequent year.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below ▼

Additional Details:

Camp - N 66 degrees 59' 9.7" and W 114 degrees 53' 51.4"
Drill locations previously reported (2007 report)

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below ▼

Additional Details:

Camp - N 66 degrees 59' 9.7" and W 114 degrees 53' 51.4"

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report Issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

--

Any additional comments or information for the Board to consider

--

Date Submitted:

June 24, 2014

Submitted/Prepared by:

Rein Lehari

Contact Information:

Tel:	416-203-8336
------	--------------

Fax:	416-368-5146
------	--------------

email:	rlehari@silvermet.ca
--------	--