



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee		Licensee Representative	
Keith Dewing Geological Survey of Canada 3303 33rd ST NW Calgary, AB T2L 2A7 Email: kdewing@NRCan.gc.ca		None Present	
Licence No. / Expiry		Representative's Title	
3BC-GLF1111 EXP. 31/12/11			
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
05/07/2014		A. Keim	
Activities Inspected			
<input checked="" type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage			
<input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Water Discharge <input checked="" type="checkbox"/> Other:			

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected					
Water Use		Condition	Comment	Site Conditions		Condition	Comment	Haz/Mat Management		Condition	Comment
Intake/Screen	NI			Water Management Structures		NA		Storage		NA	
Flow Measure. Device	NI			Culverts / Bridges		NA		Spills		NA	
Source:				Drainage		NA		Spill Plan		NA	
Water Use:	NI			Erosion / Sediment		NA					
Recirculation (y /n)	N			Mitigation Measures		NA		Administrative			
				Reclamation Activities		NA		Records		NI	
				Materials Storage		NA		Reports		C	1, 2
Waste Disposal				Signage		NA		Plans		A	
Waste Water	NA							Notifications			
Solid Waste	NA			Monitoring				Other			
Hazardous Waste	NA			Sample Collection / Analysis		NA		Comments			1
*The number in the comments field will correspond with specific comments provided below.											
Samples taken by Inspector:			Location(s):								
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No											

SECTION 1	<input checked="" type="checkbox"/> Comments (s.____)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.____)	<input type="checkbox"/> Action Required (s.____)
<p>On July 6th the Inspector attended the site listed in the 2011 Application to inspect the short term/ low impact camp and tenting sites associated with the 3BC-GLF1111 Project. Upon arrival at the general location the inspector noted that no evidence of occupation or disturbance could be seen. No persons, structures or activities could be seen in the area. The sites were both found in what appeared to be their natural state with no evidence of disturbance.</p> <p>On July 6th the Inspector attended the areas around the sites listed in the application submitted to the Nunavut Water Board. A review of the Nunavut Water Board web site (FTP site) cannot locate an Annual Report for the above noted file. As such the Inspector cannot confirm the locations as listed in the application as those actually visited by the proponent or whether or not any type of camp or overnight facilities were erected at these or other locations.</p>			
SECTION 2	<input type="checkbox"/> Comments (s.____)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.B(1))	<input type="checkbox"/> Action Required (s.____)
<p>The Licensee is in contravention of the following provision of the issued license 3BC-GLF1111:</p> <p>Part B (1) Failure to file an Annual Report on the appurtenant undertaking with the Board within sixty (60) days of completion of the field program, containing the following information:</p> <ul style="list-style-type: none">a. A summary report of water use and waste disposal activities;b. A list of unauthorized discharges and a summary of follow-up actions taken;c. A description of all progressive and or final reclamation work undertaken, including photographic records of site conditions before, during and after completion of operations;d. A summary of all information requested and results of the Monitoring Program; ande. Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.			
SECTION 3	<input type="checkbox"/> Comments (s.____)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s.____)	<input checked="" type="checkbox"/> Action Required (s.____)
<p>The Licensee has 30 days from receipt of this report to file the required Annual Report. If an annual report has been filed, the Proponent is reminded that it is the responsibility of the Licensee to ensure that all submissions to the Board are acknowledged by the licensing department and to ensure it is posted on the Nunavut Water Boards Public Registry.</p> <p>Failure to file an Annual Report within the 30 day deadline may result in further enforcement action has allowed under the Nunavut Waters and Nunavut Surface Rights Tribunal Act.</p>			

Photo Log			
Date	Authorization	Camera	Inspector
July 5, 2014	3BC-GLF1111	Sony Cyber shot	A. Keim



Figure 1 Site associated with a camp location - unconfirmed



Figure 2 Same site - Unconfirmed



Figure 3 Large deposit of salts from run off at associated location - unconfirmed



Licensee or Representative	Inspector's Name
	A.Keim
Signature	Signature
	-Sent by Email- Original on file
Date	Date
	Sept 2, 2014

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---