

## NWB Annual Report

Year being reported: 2007 ▼

License No: 8BC-TEH0708 Issued Date: February 20, 2007  
 Expiry Date: February 8, 2008

Project Name: Meadowbank Gold Project Access Road

Licensee: Cumberland Resources Limited

Mailing Address: 375-555 Burrard Street  
 Box 209, Two Bentall Centre  
 Vancouver, BC V7X 1M8  
 604-608-2557

**Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):**

In early July 2007, Cumberland Resources Limited became a 100% wholly owned subsidiary of Agnico-Eagle Mines Ltd. (AEM). Through a series of steps, AEM amalgamated with Cumberland Resources and Meadowbank Mining Corporation (a wholly owned subsidiary of Cumberland) on August 1, 2007. As a result of this amalgamation, all of the rights, title, liabilities and obligations of Cumberland Resources and Meadowbank Mining are automatically, by law, transferred and assumed by AEM.

**General Background Information on the Project (\*optional):**

**Licence Requirements: the licensee must provide the following information in accordance with**

Part B ▼ Item 2 ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	N/A - no water used along road	
Water Quantity:	N/A	Quantity Allowable Domestic (cu.m)
	N/A	Actual Quantity Used Domestic (cu.m)
	N/A	Quantity Allowable Drilling (cu.m)
	N/A	Total Quantity Used Drilling (cu.m)

**Waste Management and/or Disposal**

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

**Additional Details:**

N/A - no waste disposal activities along road

N/A - no waste disposal activities along road

#### A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

See Appendix F in the attached document for spill reporting and documentation details

#### Revisions to the Spill Contingency Plan

Other: (see additional details)

Additional Details:

Please refer to AEM's response to the INAC inspector in Appendix D of the attached document (Section C, Part G, page 14), for information regarding the spill contingency plan for the road

#### Revisions to the Abandonment and Restoration Plan

N/A - not applicable

Additional Details:

To be submitted 3 months prior to abandonment of road (Part H, Item 1 of license)

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

N/A - no reclamation work undertaken along road in 2007

#### Results of the Monitoring Program including:

\* See Section 6, 2007 Annual Report All-Weather Private Access Road

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)

Additional Details:

N/A - no water used along road

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A)

Additional Details:

N/A - no waste disposal locations along road

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Inspection and Compliance Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

INAC inspection report received by AEM September 27, 2007. See Appendix D for AEM's response.

**Any additional comments or information for the Board to consider**

**Date Submitted:**  
**Submitted/Prepared by:**  
**Contact Information:**

March 31, 2008

Rachel Lee Gould

**Tel:** 604-608-2557

**Fax:** 604-608-2559

**email:** [rgould@agnico-eagle.com](mailto:rgould@agnico-eagle.com)