

NWB Annual Report

Year being reported: 2009 ▼

License No: 2BE-BAK0709 Issued Date: February 23, 2007
 Expiry Date: November 30, 2009

Project Name: Baker Lake Project

Licensee: Tanqueray Resources Ltd.

Mailing Address: PO Box 74176
 Calgary, Alberta
 T3H 3B6

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part A ▼ Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Lake	
Water Quantity:	3.5 cu.m./day	Quantity Allowable Domestic (cu.m)
	3 cu. M /day	Actual Quantity Used Domestic (cu.m)
	56.5 cu m/day	Quantity Allowable Drilling (cu.m)
	48 cu m /day	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
☐ Sewage
☒ Drill Waste
☒ Greywater
☐ Hazardous
☐ Other:

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Revisions to the Abandonment and Restoration Plan

N/A - not applicable



Additional Details:

Drill sites are not permanent. Duration at site 1 - 3 days. Camposite is temporary wood and canvas structures.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below



Additional Details:

campsite 64° 22' 30"N 96° 37' 30"W

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below



Additional Details:

campsite 64° 22' 30"N 96° 37' 30"W
 Camp solid waste is incinerated and Bulky Items/Scrap Metal and empty fuel drums etc transported to Baker Lake Hamlet for proper disposal

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection and Compliance Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

Camp inspected by Indian and Northern Affairs on July 30, 2012
No unacceptable conditions noted.

Any additional comments or information for the Board to consider

Date Submitted:

March 24, 2014

Submitted/Prepared by:

Linda Falkenberg

Contact Information:

Tel: 403 263-9055

Fax: 403 263-9061

email: tanqueray@shaw.ca