




Water Licence: 2BE-BLU0812 Skybridge Development Corp. (subsidiary of Mega Precious Metals); KIA Land Use Permit: KTL308C001

**Inspection photographs –August 1, 2010 for the Sage Lake camp and esker sites (Blue Caribou Project) at  
coordinates N65° 13' 57" W106° 37' 06" (NAD 83)  
(Photos taken by Water Resource Officer M. Joy)**

Photograph 1: Aerial view of Sage Lake camp





CIDM#520855

**Water Licence: 2BE-BLU0812 Skybridge Development Corp. (subsidiary of Mega Precious Metals); KIA Land Use Permit: KTL308C001**

Photographs 2 & 3: (2) Fuel staging area at Sage Esker. Secondary containment is collecting water and requires reinforcement (covering is strongly recommended). (3) Pallets and woody debris left near esker fuel cache



Photographs 4 & 5: (4) Barrels placed upside-down to drain at Sage Lake camp. (5) Latrine pit, located beside latrine shack, has not been filled in and recontoured.





CIDM#520855

**Water Licence: 2BE-BLU0812 Skybridge Development Corp. (subsidiary of Mega Precious Metals); KIA Land Use Permit: KTL308C001**

Photographs 6-10: (6) Burn barrel area. (7) Debris left inside burn drum (8). (9, 10) 2 pails left outside uncovered and exposed to the elements.



Photographs 11 & 12: Debris in and around Sage Lake – (11) Spill pad and shovel; (12) Styrofoam insulation in the water.





CIDM#520855

**Water Licence: 2BE-BLU0812 Skybridge Development Corp. (subsidiary of Mega Precious Metals); KIA Land Use Permit: KTL308C001**

Photographs 13 & 14: Condition of sumps (not filled in); several propane tanks left unsecured on site (13).



Photographs 15 & 16: (15) Condition of items left in open tent frame. (16) View of some of the woody debris (nails protruding) strewn about the site.



Photograph 17 & 18: (17) View of materials stored near core shack area. (18) Battery left in tent frame.

