

indian and Northern Affairs Canada

Affaires indiennes et du Nord Canada

Qikiqtani Region P.O Box 2200 Iqaluit, NU X0A 0H0

UR Energy Inc.,
341 Main Street NORTH
Suite 206
Brampton On.
L6X 3C7
Attn: John D. Charlton / Paul Pamen.

November 5, 2009

RE: Field Inspection LUP N2008C0010. Nowleye Lake "BUGS".

On, July 25th, 2009 I conducted a field inspection at the above mentioned location.

A copy of the Inspection report is attached. After reading the report please sign and return a signed photocopy to my office. If you have any comments or suggestions please feel free to attach them to the copy of this report.

I apologize for the delay in forwarding this report to you.

## Issues Identified during the inspection:

<u>Campsite:</u> Disassembled. Core Boxes remaining. Scaring of soil from camp tents/platforms. Ash remains from incinerator evident.

Fuel Storage: No fuel caches remaining.

Water: Nothing to see.

Waste: Site is pretty well clean.

**<u>Drilling activities</u>**: One drill site located. Soil plugged hole.

<u>Comments</u>: This was a fairly clean site while it was in use and now that it's been dismantled, it is again, fairly clean. If this site is to be reopened then the permit holder must notify the Inspector at least 48 hrs in advance of re-opening.

Canad'a

Nunavut Water Board

NOV 2 9 2010

**Public Registry** 

Please do not hesitate to contact me should you have any questions or comments.

Sincerely,

Kevin L Robertson

Resource Management Officer

Qikiqtani Region

PO Box 100. Iqaluit. Nu

**X0A 0H0** 

Tel: (867) 975-4296 Fax: (867) 979-6445

Kevin.robertson@inac.gc.ca

cc: Land Administrator, INAC

CIDM # 365386



































