

NWB Annual Report

Year being reported: 2010 ▼

License No: 2BE-BUG0712

Issued Date: June 11, 2008

Expiry Date: April 30, 2012

Project Name: Bugs Project

Licensee: Ur-Energy Inc.

Mailing Address:

10758 W Centennial Road, Suite 200  
Littleton, Co. USA 80127

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (optional):

Former uranium prospection in 2007 and 2008  
No activity in 2010

Licence Requirements: the licensee must provide the following information in accordance with

Select ▼ Select ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):

none

Water Quantity:

Quantity Allowable Domestic (cu.m)

Actual Quantity Used Domestic (cu.m)

Quantity Allowable Drilling (cu.m)

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☐ Sewage☐ Drill Waste☐ Greywater☐ Hazardous☐ Other:

Additional Details:

Nunavut Water  
Board

NOV 08 2010

Public Registry

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

#### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

#### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Camp cleaned up by Sept. 2008, all remaining fuel drums removed by Kasba Lodge in 2009.

#### Results of the Monitoring Program Including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Select

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Select

Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Inspection and Compliance Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

Site inspection by INAC carried out during the summer of 2009. Clearance given as acceptable cleanup; no issues. Camp had been dismantled and everything removed in 2008 except some fuel drums which were removed by Kasba Lodge in July 2009.

**Date Submitted:**

October 25, 2010

**Submitted/Prepared by:**

Paul Pitman, VP Exploration, Canada

**Contact Information:**

Tel: 905-456-5436

Fax:

email: [pwpconsulting@bellnet.ca](mailto:pwpconsulting@bellnet.ca)