



AANDC, Nunavut District Office
Box 100
Iqaluit, NU, X0A 0H0

October 7, 2013

Deborah Chadwick
Canterra Minerals Corp.
P.O. Box 11584
Suite 1410, 650 West Georgia Street
Vancouver, British Columbia V6B 4N8
Email: dchadwick@canterraminerals.com

RE: Inspection of Water Licence 2BE-HEE0712, September 16 2013

Please find attached the report on the Water License Inspection conducted at the Heeqou Property camp, located at N65°59'08.0" W112°44'35.0".

Should you require more information or clarification on any aspect of the enclosed report please contact the undersigned at the coordinates listed below. I look forward to continuing to work with you. If you have any questions please do not hesitate to contact our office here in Iqaluit.

Sincerely,

Eva Paul
Water Resources Officer
Aboriginal Affairs and Northern Development Canada
Nunavut Regional Office
Building 918, PO Box 100
Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548
Cell | Mobile: 867-222-6490
Fax | Téléc. : 867-979-6445
Eva.Paul@aadnc-aadnc.gc.ca



WATER LICENCE INSPECTION REPORT

Date: September 16, 2013	Licensee Rep. (Name/Title): N/A
Licensee: Canterra Minerals Corp.	Licence No.: 2BE-HEE0712

Cancellation of the above licence was requested by the licensee in 2009. An inspection of the project was subsequently conducted and submitted to the Licensee which identified deficiencies to be addressed prior to cancellation of the licence.

Final reclamation was conducted in 2013. A final site inspection was conducted on September 16, 2013 by Water Resources Inspector Eva Paul, pursuant to the *Nunavut Waters and Nunavut Surface Rights Tribunal Act*.

Consistent with the compliance plan that was provided to the Inspector and the NWB, the outstanding reclamation has been completed to the satisfaction of the Inspector.

I am satisfied with the information that has been provided and with my findings on-site. Cancellation of the licence is recommended if the NWB is satisfied that administrative requirements have been met.

Eva Paul
Water Resources Officer

October 7, 2013

Date



Figure 1. Location of Heeqou Camp - visible outline.




Figure 2. Tent outline - Regrowth visible.