



AANDC, Nunavut District Office  
Box 100  
Iqaluit, NU, X0A 0H0

October 9, 2013

Deborah Chadwick  
Canterra Minerals Corp.  
P.O. Box 11584  
Suite 1410, 650 West Georgia Street  
Vancouver, British Columbia V6B 4N8  
Email: [dchadwick@canterraminerals.com](mailto:dchadwick@canterraminerals.com)

**RE: Inspection of Water Licence 2BE-PER0610, September 16 2013**

Please find attached the report on the Water License Inspection conducted at the Peregrine Project camp location (N67°08'27.6" W113°35'34.8").

Should you require more information or clarification on any aspect of the enclosed report please contact the undersigned at the coordinates listed below. I look forward to continuing to work with you. If you have any questions please do not hesitate to contact our office here in Iqaluit.

Sincerely,

Eva Paul  
Water Resources Officer  
Aboriginal Affairs and Northern Development Canada  
Nunavut Regional Office  
Building 918, PO Box 100  
Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548  
Cell | Mobile: 867-222-6490  
Fax | Téléc. : 867-979-6445  
[Eva.Paul@aadnc-aadnc.gc.ca](mailto:Eva.Paul@aadnc-aadnc.gc.ca)



## WATER LICENCE INSPECTION REPORT

<b>Date:</b> September 16, 2013	<b>Licensee Rep. (Name/Title):</b> N/A
<b>Licensee:</b> Canterra Minerals Corp.	<b>Licence No.:</b> 2BE-PER0610

Cancellation of the above licence was requested by the licensee in 2009. An inspection of the project was conducted and submitted to the Licensee which identified deficiencies to be addressed prior to cancellation of the licence.

Final reclamation was conducted in 2013. A final site inspection was conducted on September 16, 2013 by Water Resources Inspector Eva Paul, pursuant to the *Nunavut Waters and Nunavut Surface Rights Tribunal Act*.

Consistent with the compliance plan that was provided to the Inspector and the NWB, the outstanding reclamation has been completed to the satisfaction of the Inspector.

*I am satisfied with the information that has been provided and with my findings on-site. Cancellation of the licence is recommended if the NWB is satisfied that administrative requirements have been met.*

**Eva Paul**  
**Water Resources Officer**

October 9, 2013

**Date**





**Figure 1. Peregrine Camp from the air. Prominent flagstones have been removed and dispersed.**



**Figure 2. Holes were backfilled with appropriate material.**