

NWB Annual Report

Year being reported: 2006 ▼

License No: 2BE-PER0610 **Issued Date:** May 24, 2006
Expiry Date: December 10, 2010

Project Name: Peregrine Property

Licensee: Diamondex Resources Ltd.

Mailing Address: P.O. Box 11584
 1410 - 650 West Georgia Street
 Vancouver, BC
 V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Same as above

General Background Information on the Project (*optional):

The Peregrine camp was not occupied in 2006. No work was conducted therefore no water was used and no waste deposited.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

| | | |
|------------------|--|--------------------------------------|
| Water Source(s): | Domestic - unnamed lake adjacent to the camp | |
| Water Quantity: | 5 cu.m/day | Quantity Allowable Domestic (cu.m) |
| | 0 cu.m/day | Actual Quantity Used Domestic (cu.m) |
| | 20 cu.m/day | Quantity Allowable Drilling (cu.m) |
| | 0 cu.m/day | Total Quantity Used Drilling (cu.m) |

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

There was no work conducted on this property in 2006.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There were no spills.

Revisions to the Spill Contingency Plan

Other: (see additional details) ▼

Additional Details:

A revised Spill Contingency Plan was submitted with our Water Licence Renewal Application, granted in 2006.

Revisions to the Abandonment and Restoration Plan

Other: (see additional details) ▼

Additional Details:

A revised Abandonment and Restoration Plan was submitted with our Water Licence Renewal Application, granted in 2006.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

To date there has been no reclamation work undertaken.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

There was no work conducted on this property in 2006.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

There was no work conducted on this property in 2006.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 13, 2007

Submitted/Prepared by:

Janet Stritychuk, Land Manager

Contact Information:

Tel: (604) 687 6644

Fax: (604) 687 1448

email: jstrychuk@diamondex.net