

NWB Annual Report

Year being reported: 2009 ▼

License No: 2BE-TIM0813

Issued Date: August 27, 2008

Expiry Date: June 27, 2013

Nunavut Water
Board

DEC 31 2012

Public Registry

Project Name: TIM Project

Licensee: Diamondex Resources Ltd.

Mailing Address:

P.O. Box 11584
650 West Georgia Street, Suite 1410
Vancouver, British Columbia V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼

Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

None used

Water Quantity:

None

Quantity Allowable Domestic (cu.m)

None used

Actual Quantity Used Domestic (cu.m)

50 m³/day

Quantity Allowable Drilling (cu.m)

None used

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☐ Sewage☐ Drill Waste☐ Greywater☐ Hazardous☐ Other:

Additional Details:

No work was done in 2009

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Additional Details:

Revisions to the Abandonment and Restoration Plan

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider**Date Submitted:****Submitted/Prepared by:****Contact Information:****Tel:** **Fax:** **email:**