

WATER USE INSPECTION REPORT FORM

| | |
|--|---|
| Date: July 13th,2011 | Licensee Rep. (Name/Title): Jennie Rausch |
| Licensee: Canadian Wildlife Service –Arctic Shorebird Monitoring Program | Licence No3BC-ASM1010 (expired) |

WATER SUPPLY

| | |
|--|--|
| Source(s): Lakes adjacent to Camp site | Quantity used: .36 cubic M .. as per Annual report |
| Owner:/Operator: Canadian Wildlife Service | |

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | | |
|-----------------------|-----------------------|----------------------|----------------------|
| Intake Facilities: NA | Storage Structure: NA | Treatment Sys: NA | Chemical Storage: NA |
| Flow Meas. Device: NA | Conveyance Lines: NA | Pumping Stations: NA | Screen : NA |

Comments: Closure Inspection conducted July 13, 2011. No water usage at time of inspection.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Latrine pit system

| | | |
|------------------------|--|------------|
| Natural Water Body: NA | Continuous Discharge (land or water): None | |
| Seasonal Discharge: NA | Wetlands Treatment: NA | Trench: NA |

Comments: No evidence of waste disposal found on site at time of Inspection.

Solid Waste:

| | | |
|----------------|---------------------|-----------------|
| Landfill: None | Burn & Landfill: NA | Other: backhaul |
|----------------|---------------------|-----------------|

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | |
|----------------------------|-----------------------------|-----------------------|
| Discharge Quality: NA | Decant Structure: NA | Erosion: NA |
| Discharge Meas. Device: NA | Dyke Inspection: NA | Seepages: NA |
| Dams, Dykes: NA | Freeboard: NA | Spills: None reported |
| Construction: NA | O&M Plan: NA | A&R Plan: NA |
| Periods of Discharge: NA. | Effluent Discharge Rate: NA | |

Comments: No evidence of waste left on site was found during Inspection. Annual report indicates that wastes were back hauled to Cambridge Bay.

FUEL STORAGE:

Waste Oil Storage: None noted Owner/Operator: NA

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | |
|------------------------|------------------------------------|-----------------------|
| Berms & Liners: NA | Water within Berms: NA | Evidence of Leaks: NA |
| Drainage Pipes: NA | Pump Station & Catchments Berm: NA | |
| Pipeline Condition: NA | Condition of Tanks: NA | |

Comments: An Inspection was conducted at the Fuel cache location and No drums belonging to the project were found on site.

SURVEILLANCE NETWORK PROGRAM (SNP)

| | | |
|--------------------------|--|-------------|
| Samples Collected | Owner /Operator: NA | |
| 0 | INAC: NA | |
| Signs Posted | SNP: NA | Warning: NA |
| Records & Reporting: | Annual reporting was noted on the Nunavut Water Board FTP site | |
| Geotechnical Inspection: | N/A | |

NON-COMPLIANCE OF ACT OR LICENCE: None.

The Inspector recommends that, pending a request from the Licensee, the License file be closed.

A.Keim

Inspector’s Name

Sent by E-mail

Inspector’s Signature