



Aboriginal Affairs and
Northern Development Canada

Affaires autochtones et
Développement du Nord Canada

March 20, 2012 Inspection Photos

Eva Paul, Water Resources Officer
AANDC



Water Pump House



Tank for backup generator at Water Pump House – berm full of snow.



Berm under tank at heli-pad. Wall is torn and berm is full of snow.



Waste oil (?) being transferred into lined sea-cans.



Waste segregation process appears to be working well.



Unidentified substance beside Nuna Shop



Example of drip tray / absorbent that is working well.



Batteries not stored consistently in McCaw North shop.



No drip tray or absorbent under drill outside McCaw North shop.



Old burn pan



New burn pan



Barrels at Airport



Unidentified substance behind airport building