

95 Wellington Street Suite 1010 Toronto, Ontario M5J 2N7 416-628-0216

## **Sent by Email**

## December 24, 2018

Jeremy Fraser - <u>jeremy.fraser@canada.ca</u>
Water Resources Officer
Crown-Indigenous Relations and Northern Affairs Canada
PO Box 2200
Iqaluit, NU
X0A 0H0

## Re: TMAC Response to CIRNAC Inspection Report for Surface Lease 77A/3-1-7, October 11, 2018

Dear Mr. Fraser,

TMAC Resources Inc. (TMAC) is providing this letter in response to action items identified in the 77A/3-1-7 Surface Lease Inspection Report provided by Crown Indigenous-Relations and Northern Affairs Canada (CIRNAC) on December 4, 2018. Action items and TMAC's response are detailed below:

A. During inspection of the Jetty, the Inspector observed debris such as wood, ropes, boat anchors, ramps, and a floating dock. Some of the wood on the Jetty appears to have been wind blown into the ocean. Shipping ramps and floating dock were still lingering although the sea lift season had been completed. Embankments appear to be in good condition and were to the satisfaction of the Inspector.

The Inspector noted that TMAC has restored the Jetty to the satisfaction of the Inspector throughout the course of this inspection.

Action Required: TMAC has provided photos of the Jetty to satisfy the Inspector of all concerns related to this Land Lease have been addressed.

**TMAC Response**: TMAC removed the wood, ropes, boat anchors and floating dock prior to completion of the inspection to the satisfaction of the Inspector. With permission from the Inspector, a shipping ramp has been left in place on the jetty to facilitate inspections of a tug boat and cargo barge that was iced in at the end of the sealift season. This shipping ramp will be removed prior to freshet in 2019 as requested by the Inspector.

Should you have any further questions please feel free to contact me at <a href="mailto:enviro@tmacresources.com">enviro@tmacresources.com</a>.

Sincerely,

Kyle Conway

Environmental Supervisor

TMAC Resources Inc.

Cc:

Nunavut Water Board

Oliver Curran, Vice President - Environmental Affairs, TMAC

Dan Gagnon, Mine General Manager, TMAC

Attachments:

Attachment A – Photograph of Doris Cargo Jetty

Attachment A – Condition of the Doris cargo jetty restored to the satisfaction of the inspector.

