

3/4" Crush Sample from Crusher - Sieve Results

Kurylo, John

Sent: Saturday, April 30, 2011 8:12 PM
To: Mark Valeriote [markv@jdsmining.ca]; Wade, Lowell; Rykaart, Maritz
Cc: Garry Dang-Vuu (gvuu@eba.ca); Liu, Guanfu [gliu@eba.ca]; Miller, Megan; Bay, Hope; Kurylo, John; Miskolczi, Iozsef; Jeff Orr [JOrr@eba.ca]
Attachments: HB-CR-BEDDING-PSD 01-QC-20~1.pdf (57 KB)

Hey Mark,

Yes sampling of the ¾" crush was completed on April 28th and again today. The sample from today is still in progress. On April 29th a sample was not taken at the dam due to a focus on the North Dam liner installation and FCM placement.

Please find attached the results for the April 28th ¾" sample. Note the sieve was completed with the sieves that we have readily available on site.

Kind Regards,

John
jkurylo@srk.com

Staff Consultant, *EIT*
SRK Consulting (Canada) Inc.
Suite 2200, 1066 West Hastings Street
Vancouver, V6E 3X2, Canada
Tel: +1-604-681-4196; **Fax:** +1-604-687-5532
Direct: +1-604-628-2570

From: Mark Valeriote [mailto:markv@jdsmining.ca]
Sent: Saturday, April 30, 2011 4:18 PM
To: Kurylo, John
Subject: 3/4" Crush

Hello John,

Did SRK/EBA obtain samples of the 3/4" crush over the last few days?

Mark


SIEVE ANALYSIS REPORT

Washed Sieve: ASTM C136 and C117

Project No.: E14101112
Project: Doris North - North Dam
Client: SRK Consulting (Canada) Inc.
Attention: Lowell Wade
Email: hopebay@srk.com
Description: Bedding Material
Source: Quarry 2
Supplier: Nuna
Sample Location: Crusher Belt
Specification: SRK Consulting Specification Revision G Bedding Material

Sample No.: 211
Date Received: April 28, 2011
Sampled by: JJJ/GDV
Date Tested: April 28, 2011
Tested by: GDV Office: On-site lab
Moisture Content (as received): 1.0%
No. Crushed Faces: Two (2) or Three (3)
By Particle Mass: _____

Sieve Size	Percent Passing
20	100
12.5	91
10.0	77
5	45
2.5	27
1.25	17
0.630	11
0.315	8
0.160	6
0.080	4.3



Remarks: File name: HB-CR-BEDDING-PSD 01-QC-20110428

Reviewed By: _____