

APPENDIX K
Inspection Acceptance and Sign-Off Forms

Inspection Acceptance and Sign-Off Form

Project Name:	Hope Bay Project
Description of Area Inspected:	<i>Location: Doris North-Pad "B"</i> <i>Area: Permanent Power Genset Foundation</i>
Date of Inspection:	July 20, 2011
Parties Present at Inspection	Bradford Watkin, Nuna Quality Manager. Lawrence Borowski, P Eng, SRK Field Engineer.

Comments:		
<p>A final inspection of was conducted of Permanent Power Genset Foundation area that was excavated to the ROQ layer and rebuilt to a new elevation. The ROQ was then re-introduced and compacted to bring the ROQ layer to the specified elevation. Then the ¾" crush capping was placed and compacted.</p> <p>It was found to be acceptable at time of inspection to the SRK Specification (Latest Revision).</p> <p>Note: See appended Survey drawing for surveyed outline of the above approved area.</p>		
<u>Contractor:</u>	<u>BRADFORD WATKIN</u> Name	<u>Aug 16, 2011</u> Date
<u>Engineer-of-Record:</u>	<u>LAWRENCE BOROWSKI</u> Name	<u>Aug 16/11</u> Date

Acceptance:		
<p>These works have been built in accordance with the Project Technical Specifications and Construction Drawings provided by the Engineer.</p>		
<u>Contractor:</u>	<u>BRADFORD WATKIN</u> Name	<u>Aug 16, 2011</u> Date
<u>Engineer-of-Record:</u>	<u>LAWRENCE BOROWSKI</u> Name	<u>Aug 16/11</u> Date