

Hope Bay Mining Project



Inspection Acceptance and Sign-Off Form

| Project Name: | Hope Bay Project |
|----------------------------------|---|
| Description of Area Inspected: | Location: Doris North Area: Land Farm |
| Date of Inspection: | August 14, 2011 |
| Parties Present at Inspection | Bradford Watkin, Nuna Quality Manager. Lawrence Borowski, P. Eng SRK Field Engineer. |

Comments:

A final inspection of was conducted of the Doris North Landfarm the following items were inspected: Location, Final surface elevation, Fill quality and gradation, Liner installations, Surface cover thickness, Extent, and Gradation.

It was found to be acceptable at time of inspection to the IFC drawings and SRK Specification (Latest Revisions).

Note: See appended Survey drawing for surveyed outline of the above approved area.

Contractor:

Name

Signature

Date

Engineer-ofRecord:

Name

Signature

Signature

Date

Date

Acceptance:

These works have been built in accordance with the Project Technical Specifications and Construction Drawings provided by the Engineer.

Contractor: BRANFORD WATK

Name Signature

Name Signature Barowski Bato

Engineer-of-Record: