







Inspection Acceptance and Sign-Off Form

Project Name:	Hope Bay Project
Description of Area Inspected:	<i>Doris North-Water Management Sumps Project: Sump 1 and 2 construction and installation</i>
Date of Inspection:	<i>April 25th, 2012</i>
Parties Present at Inspection	<i>Mike Price Nuna Lawrence Borowski SRK</i>

Comments:
<i>Sumps 1 and 2 have been completed as per the engineer's specification and the approved RFI's.</i>
Note: <i>Outstanding survey data on the annulus will follow at a later date when an accurate survey can be completed. The backfilled till elevation will be monitored and topped up as required during the summer months.</i>

Acceptance:		
These works have been built in accordance with the Project Technical Specifications and IFC Construction Drawings provided by the engineer.		
<u>Contractor:</u>	 Name	 Signature
		 Date
<u>Engineer-of-Record:</u>	 Name	 Signature
		 Date