

## Inspection Acceptance and Sign-Off Form

<b>Project Name:</b>	Hope Bay Project
<b>Description of Area Inspected:</b>	<i>Doris North- Pollution/Sedimentation Pond Thermistors Installation</i>
<b>Date of Inspection:</b>	<i>April 10, 2012</i>
<b>Parties Present at Inspection</b>	<i>Gary Sodhi, Nuna Contracting Ltd. Lawrence Borowski, SRK Consulting Inc.</i>

<p><b>Comments:</b></p> <p><i>All 3 thermistor strings at the Poll/Sed Ponds were installed as per SRK's specifications. The thermistor strings were tested prior and following the installation and were determined to be in working condition. The design was modified by adding a base layer of 6" crush to provide additional stability for the thermistor corridor. The SRK representative approved the above said change.</i></p> <p><i>The junction boxes will also be installed once they are manufactured by TliCho.</i></p>
---

<b>Installation Complete</b>			
<u>Contractor:</u>	<i>Gary Sodhi</i> Name	<i>[Signature]</i> Signature	<i>11-April-2012</i> Date
<u>Engineer-of-Record:</u>	<i>Lawrence B. Borowski</i> Name	<i>[Signature]</i> Signature	<i>11-April-2012</i> Date