



95 Wellington Street West  
Suite 1010  
P.O. Box 44  
Toronto,  
Ontario  
M5J 2N7

January 14, 2015

Phyllis Beaulieu  
Manager of Licensing  
Nunavut Water Board  
P.O. Box 119  
Gjoa Haven, NU  
X0B 1J0

**Re: December 2014 – Monthly Monitoring Report for Water Licence 2AM-DOH1323**

---

This report is comprised of monitoring requirements as set out in Part J and Schedule J of water licence 2AM-DOH1323, and additional requirements from AANDC. Licence items include:

- Part E (Conditions applying to Water Use) Item 1;
- Part G (Conditions Applying to Waste Management and Waste Management Plans) Items 1, 3(b) and 23 (a), 24 (c, e), 28, 29, 30, 32;
- Part J (Conditions Applying to General and Aquatic Effects Monitoring) Items 4(a), 8, 12 (a, d, g), 14, 15, 16, 20 and 21(e, f).

Other monitoring requirements stipulated in the licence refer to facilities that have not been constructed. Doris Camp is currently operating in a care and maintenance phase with water management, surface exploration, and environmental compliance being the focus of current activities. Sampling locations monitored under this licence (seasonally or when facilities are operational) are provided in Figure 1.

**Part E: Conditions Applying to Water Use**

**Item 1: Water Usage and Part J, Item 12(a) Water Volume**

91m<sup>3</sup> of water was extracted from Windy Lake for Doris Camp domestic use this month as permitted by water licences 2BE-HOP1222 and 2AM-DOH1323. Water was not used for drilling in support of the Doris North mine as exploration was completed for the year on Nov. 17, 2014. No water was used for dust suppression or ice road building this month. Water usage is presented in Table 1.

Table 1: Water usage, in cubic meters, December 2014

Water Usage	Domestic Water Use from Windy Lake ST-7a (m <sup>3</sup> )	Annual Cumulative (m <sup>3</sup> )
Monthly Total	91	7440

## Schedule J: Water Quality Monitoring at Water Intake

Monthly water quality samples were taken from monitoring station ST-7A (Windy Lake raw water) in accordance with the Schedule J requirements of the licence. Water quality results are presented in Table 2 below. Water was not sampled at ST-7 (Doris Lake raw water) this month as the Doris Lake Pumphouse was not operating.

Table 2: Monthly Compliance Sample Results for ST-7a, December 2014

		Sample ID	ST7A-16DEC14
		ALS ID	L1559280-1
		Date Sampled	12/16/2014
Parameter	Units	Detection Limit	Water
Hardness (as CaCO <sub>3</sub> )	mg/L	0.5	84.7
pH	pH	0.1	8.01
Total Suspended Solids	mg/L	3	<3.0
Ammonia, Total (as N)	mg/L	0.005	0.0116
Nitrate (as N)	mg/L	0.005	<0.0050
Nitrite (as N)	mg/L	0.001	<0.0010
Orthophosphate-Dissolved (as P)	mg/L	0.001	0.0016
Phosphorus (P)-Total	mg/L	0.002	0.0061
Cyanide, Total	mg/L	0.005	<0.0050
Cyanide, Free	mg/L	0.005	<0.0050
Fecal Coliforms	CFU/100mL	1	<1
Total cyanobacterial cell count	cells/mL	1	<1*
Aluminum (Al)-Total	mg/L	0.005	0.0142
Antimony (Sb)-Total	mg/L	0.0005	<0.00050
Arsenic (As)-Total	mg/L	0.0005	<0.00050
Barium (Ba)-Total	mg/L	0.02	<0.020
Beryllium (Be)-Total	mg/L	0.001	<0.0010
Boron (B)-Total	mg/L	0.1	<0.10
Cadmium (Cd)-Total	mg/L	0.00001	<0.000010
Calcium (Ca)-Total	mg/L	0.1	14.7
Chromium (Cr)-Total	mg/L	0.001	<0.0010
Cobalt (Co)-Total	mg/L	0.0003	<0.00030
Copper (Cu)-Total	mg/L	0.001	<0.0010
Iron (Fe)-Total	mg/L	0.03	<0.030
Lead (Pb)-Total	mg/L	0.0005	<0.00050
Lithium (Li)-Total	mg/L	0.005	<0.0050
Magnesium (Mg)-Total	mg/L	0.1	11.6
Manganese (Mn)-Total	mg/L	0.0003	0.00084
Mercury (Hg)-Total	mg/L	0.00001	<0.000010
Molybdenum (Mo)-Total	mg/L	0.001	<0.0010
Nickel (Ni)-Total	mg/L	0.001	<0.0010
Potassium (K)-Total	mg/L	2	4.6
Selenium (Se)-Total	mg/L	0.0001	<0.00010
Silver (Ag)-Total	mg/L	0.00002	<0.000020
Sodium (Na)-Total	mg/L	2	64.5
Thallium (Tl)-Total	mg/L	0.0002	<0.00020
Tin (Sn)-Total	mg/L	0.0005	<0.00050
Titanium (Ti)-Total	mg/L	0.01	<0.010
Uranium (U)-Total	mg/L	0.0002	<0.00020
Vanadium (V)-Total	mg/L	0.001	<0.0010
Zinc (Zn)-Total	mg/L	0.005	<0.0050
Biochemical Oxygen Demand	mg/L	2	2
Oil and Grease	mg/L	5	<5.0
Oil And Grease (Visible Sheen)		n/a	No
Microcystin	ug/L	0.2	<0.20*

\* results on Lab Work Order L1559322 for Station PDC10 (Windy Lake Potable Drinking Water Sampling Station)

**Part G: Conditions Applying to Waste Management and Waste Management Plans.****Item 1: Condition to Provide Notice of a Planned Discharge**

Notification of planned discharges from facilities under this licence was provided to the Inspector May 24, 2014. No discharges are occurring as all facilities are now frozen.

**Item 3(b): Conditions Applying to Sewage Effluent Quality and Schedule J, Table 2 Monitoring Requirements: Discharge from Wastewater Treatment Plant in cubic metres.**

Monthly compliance samples were taken from monitoring station ST-8 (Wastewater Treatment Plant Effluent) in accordance with the Schedule J requirements of the licence (Table 3). All parameters were in compliance with discharge criteria.

Table 3: Monthly Compliance Sample Results for ST-8B, December 2014

Sample ID			ST8B-02DEC14	Part G Item 3(b)	
ALS ID			L1553772-1	Maximum Average Concentration (mg/L)	Maximum Concentration in any Grab Sample (mg/L)
Date Sampled			12/02/2014 10:00		
Parameter	Units	Detection Limit	Water		
pH	pH	0.1	7.91	6.0 - 9.0	9.0
Total Suspended Solids	mg/L	3	<3.0	100	100
Fecal Coliforms	CFU/100mL	1	<1	10,000	10,000
Biochemical Oxygen Demand (BOD <sub>5</sub> )	CFU/100 mL	1	<2.0	80	80
Oil and Grease	mg/L	5	<5.0	5	10
Oil And Grease (Visible Sheen)		n/a	No	No Visible Sheen	No Visible Sheen

This month, 69m<sup>3</sup> of sewage effluent was discharged from the sewage treatment plant.

**Schedule J, Table 2 Monitoring Requirements: Runoff from Waste Water Treatment Plant Discharge (ST-9)**

No water was available for sampling at location ST-9 (prior to entry into Glenn Lake) due to freezing conditions.

**Item 23(a): Water Discharged from the Sedimentation Pond (ST-1) and Reagent and Cyanide Storage Facility Sumps (ST-11) and Schedule J, Table 2 Monitoring Requirements**

As described in the 2012 Interim Water Management Plan, the Sedimentation Pond (ST-1) is being used as a collection pond for the water that accumulates in the Pollution Control Pond (ST-2), the two Underflow Sumps (ST2S1 and ST2S2), and occasionally from various berms and containments in the project area. The water in ST-1 is transferred to the Tailings Impoundment Area (TIA) when there is enough accumulated water for the pumps to operate effectively. At this time, no ST-1 water is being discharged to the tundra. Transfer of water from ST-1 to the TIA was initiated May 30, 2014 and concluded September 25, 2014. No water was discharged at ST-1 this month.

The Reagent and Cyanide Storage Facility Sumps (ST-11) is not constructed. Due to freezing conditions, monitoring could not be undertaken at the Pollution Control Pond (ST-2) this month. The pumping of water from the Pollution Control Pond (ST-2) to the Sedimentation Pond (ST-1) was concluded on September 26, 2014.

**Items 24(c): Landfarm Sump (ST-4) and Schedule J, Table 2 Monitoring Requirements**

Compliance samples were not required from monitoring station ST-4 (Landfarm Sump) in accordance with the Schedule J requirements of the licence; no water was discharged from the facility during the month.

**Items 24(e): Fuel Storage and Containment Facility Sumps (ST-5, ST-6a and ST-6b) and Schedule J, Table 2 Monitoring Requirements**

Compliance monitoring samples were not collected at the Doris Tank Farm (ST-5) and Roberts Bay tank farms (ST-6a and ST-6b) this month. These facilities are empty and no discharges occurred.

**Item 28, 29, 30 and Part J Item 8: Water Quality Discharged from Tailings Impoundment Area (TL-1, TL-2, TL-3 or TL-4.)**

Due to freezing conditions all discharge from the TIA to Doris Creek was concluded on September 25, 2014. Compliance water sampling was not conducted this month at the four stations associated with the TIA discharge (TL-1 through TL-4) as no water was discharged from this facility.

**Item 32: Tailings Impoundment Area Discharge Volume – Comparison of Flows at TL-4 and TL-2**

Water was discharged from the TIA starting June 19, 2014 and continued to September 25, 2014 at which time freezing conditions prevented ongoing pumping. No water was discharged from the TIA to Doris Creek this month; a comparison of flows was not conducted.

**Schedule J: Tailings Impoundment Area Water Quality (TL-10)**

Monitoring at TL-10 is not required during Care and Maintenance.

**Part J: Conditions Applying to General and Aquatics Effects Monitoring**

**Item 4(a): TIA Discharge Quality – Water Quality Comparison/Deviations**

No water was discharged from the TIA this month and no water quality comparisons were made.

**Item 8 and Schedule J, Monitoring Requirements: Acute Lethality Testing (TL-1 and TL-4)**

No acute lethality testing was conducted during the month. Acute lethality testing was conducted prior to the start of TIA dewatering and once during the discharge period earlier in the season.

**Item 12d: Tonnages of Waste Rock Stored on the Temporary Waste Rock Pad**

Underground mining did not occur during the month. The total volume of waste rock on the temporary waste rock pad is 189,607 tonnes, as per the December 2011 survey.

**Item 12g: Tail Lake Ice Thickness**

Ice thickness measurement at Tail Lake is not required during Care and Maintenance.

**Item 14, 15, 16 and Schedule J, Monitoring Requirements: Thermal Monitoring**

Thermal monitoring undertaken under this part is reported in the annual Geotechnical Inspection Report.

**Item 20: Daily Visual Monitoring of Discharges to Tundra**

No discharges to tundra occurred during this period. During periods of discharge, monitoring observations will be documented.

**Item 21 (e) Daily Visual Assessment of Suspended Sediment at TIA**

The TIA was frozen during this month. No visual assessments were conducted.

**Item 21 (f) Doris North Camp Diversion Berm Effectiveness**

An assessment of effectiveness was not conducted on the Diversion Berm this month due to freezing conditions.

**Environmental Incident Reporting**

No environmental incidents occurred during the month.

Should there be any questions regarding this monthly report, please contact John Roberts at [John.Roberts@tmacresources.com](mailto:John.Roberts@tmacresources.com).

Yours sincerely,



M. John Roberts  
Vice President, Environmental Affairs  
Hope Bay Project  
(416) 628-0216

cc. Eva Paul, Water Resources Officer, AANDC

Figure 1. 2AM-DOH1323 SNP Monitoring Locations

