


Notes:

- 1. Depression locations are based on hand held GPS measurements, accuracy is at best +/- 4 m.
- 2. Most photos courtesy of TMAC site personnel

				2015 North Dam Geotechnical Inspection	
Job No: 1CT022.002 Filename: Ndam_DepressionTracking.pptx		HOPE BAY MINING LTD.		Depression Tracking D9	
				Date: Oct. 2015	Approved: PDL Figure: H.18



Notes:

1. Depression location on field inspection sketches.
2. Most photos courtesy of TMAC site personnel



Job No: 1CT022.002
Filename: Ndam_DepressionTracking.pptx




HOPE BAY MINING LTD.

2015 North Dam Geotechnical Inspection

**Depression Tracking
D10**

Date: Oct. 2015	Approved: PDL	Figure: H.19
--------------------	------------------	------------------------



- Notes:**
1. Depression location on field inspection sketches.
 2. Most photos courtesy of TMAC site personnel

		2015 North Dam Geotechnical Inspection		
		Depression Tracking D11		
Job No: 1CT022.002 Filename: Ndam_DepressionTracking.pptx	HOPE BAY MINING LTD.	Date: Oct. 2015	Approved: PDL	Figure: H.20