

PHOTOGRAPHS

Photo 1	Till Fill Pad construction at Reach A inlet, facing south
Photo 2	Reach A inlet key trench, looking southeast
Photo 3	Reach A inlet key trench, looking northwest
Photo 4	Bringing Reach A inlet alignment to grade, facing southwest
Photo 5	Reach A inlet alignment, facing southwest
Photo 6	Reach A inlet, facing southwest
Photo 7	Backfilling Reach A key trench, facing southeast
Photo 8	Reach A inlet structure complete, facing southwest
Photo 9	Reach A channel excavation facing south from Carat Lake Road culvert
Photo 10	Reach B excavated and shaped, facing west
Photo 11	Reach B complete, facing southwest
Photo 12	Placing north till berm in Reach C, facing northeast
Photo 13	Reach C north berm complete, facing northeast
Photo 14	Upper pool in Reach C completed



Photo 1: Till fill pad construction at Reach A inlet, facing south. Spreading till with D9 dozer. Photo taken March 17, 2006.



Photo 2: Reach A inlet key trench, looking southeast. Note vertical rock face at end of key trench. Photo taken April 24, 2006.



Photo 3: Reach A inlet key trench, looking northwest. Photo taken April 24, 2006.



Photo 4: Bringing Reach A inlet alignment to grade, facing southwest. Packing 150 mm material prior to placing liner bedding. West slope has been grubbed. Some fill still required to smooth sharp contours. Photo taken April 24, 2006.



Photo 5: Reach A inlet alignment, facing southwest. Till pad and west slope have been shaped. Some additional liner bedding to be placed on till slope in foreground of photo. Photo taken April 26, 2006.



Photo 6: Reach A inlet, facing southwest. HDPE liner installation in progress.



Photo 7: Backfilling Reach A key trench, facing southeast. Material spread with bobcat and compacted with tamper. Photo taken May 7, 2006.



Photo 8: Reach A inlet structure complete, facing southwest. Photo taken May 22, 2006.



Photo 9: Reach A channel excavation facing south from Carat Lake Road culvert. Photo taken May 22, 2006.



Photo 10: Reach B excavated and shaped, facing west. Photo taken May 26, 2006.



Photo 11: Reach B complete, facing southwest. Photo taken May 22, 2006.




Photo 12: Placing north till berm in Reach C, facing northeast. Photo taken May 4, 2006.



Photo 13: Reach C north berm complete, facing northeast. Upper pool in foreground. Photo taken May 22, 2006.



Photo 14: Upper pool in Reach C completed. Photo taken May 4, 2006.