





STATUS ISSUED FOR USE		CLIENT		GENERAL MONITORING PLAN JERICHO DIAMOND MINE, NUNAVUT	
MONITORING LOCATIONS:		shear diamonds		CATCHMENT AREAS AND SWQ SITE WATER QUALITY MONITORING LOCATION	
■	- SWF, SITE WATER FLOW MONITORING LOCATION			PROJECT NO. E14101118	
●	- SWQ, SITE WATER QUALITY MONITORING LOCATION				
▲	- SPG, SEEPAGE SURVEY LOCATION	A TETRA TECH COMPANY		DATE January 31, 2011	Figure 3b





NOTE:
PROCESSED KIMBERLITE CONTOURS EXTRAPOLATED
FROM APRIL 22, 2008 SURVEY.



- MONITORING LOCATIONS:
- - WATER QUALITY MONITORING LOCATIONS
 - - PROPOSED WATER PIPELINE ROUTE



CLIENT		PIT DEWATERING MANAGEMENT PLAN JERICHO DIAMOND MINE, NUNAVUT		
		EXISTING PKCA PLAN		
 A TERNATECH COMPANY		Figure 2		
PROJECT NO.	DATE	OWN	CD	REV
E1410118.002	DRG/TK	WL		0
OFFICE	DATE			
EBA-EDM	May 2011			