



Canada

# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

<b>A</b>	REPORT DATE: MONTH – DAY – YEAR <b>April 4, 2012</b>	REPORT TIME <b>13:00</b>	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
<b>B</b>	OCCURRENCE DATE: MONTH – DAY – YEAR <b>April 3-4, 2012</b>	OCCURRENCE TIME <b>18:00 - 11:00</b>		
<b>C</b>	LAND USE PERMIT NUMBER (IF APPLICABLE) <b>KTL 311 C015</b>	WATER LICENCE NUMBER (IF APPLICABLE) <b>2AM-JER1119</b>		
<b>D</b>	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION <b>Jericho Mine Site</b>	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
<b>E</b>	LATITUDE DEGREES <b>66</b> MINUTES <b>01</b> SECONDS <b>00</b>	LONGITUDE DEGREES <b>111</b> MINUTES <b>27</b> SECONDS <b>00</b>		
<b>F</b>	RESPONSIBLE PARTY OR VESSEL NAME <b>Shear Diamonds</b>	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>Suite 220, 6 Adelaide St. E, Toronto, ON</b>		
<b>G</b>	ANY CONTRACTOR INVOLVED <b>no</b>	CONTRACTOR ADDRESS OR OFFICE LOCATION <b>n/a</b>		
<b>H</b>	PRODUCT SPILLED <b>Diesel</b>	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>10L</b>	U.N. NUMBER <b>1202</b>	
	SECOND PRODUCT SPILLED (IF APPLICABLE) <b>none</b>	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>n/a</b>	U.N. NUMBER <b>n/a</b>	
<b>I</b>	SPILL SOURCE <b>fuel line</b>	SPILL CAUSE <b>open valve</b>	AREA OF CONTAMINATION IN SQUARE METRES <b>1.0</b>	
<b>J</b>	FACTORS AFFECTING SPILL OR RECOVERY <b>none</b>	DESCRIBE ANY ASSISTANCE REQUIRED <b>none</b>	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT <b>none</b>	
<b>K</b>	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <b>-secondary fuel line at airport generator has a valve on the end of it that was left slightly open causing a slow leak</b> <b>-diesel leaked out overnight in the sea-can where the generator is located and eventually leaked outside the main door of the sea-can, covering snow an area of about 1 square meter</b> <b>-leak was discovered around 11am on April 4, 2012 and the valve was properly closed</b> <b>-all contaminated snow was shovelled up and disposed of in the truck shop, sea-can was cleaned up</b> <b>-secondary fuel line is now capped off so that leak will not reoccur</b>			
<b>L</b>	REPORTED TO SPILL LINE BY <b>Wes Atchison</b>	POSITION <b>Environmental Tech.</b>	EMPLOYER <b>Shear Diamonds</b>	LOCATION CALLING FROM <b>Jericho Mine Site</b>
			TELEPHONE <b>778-372-2723</b>	
<b>M</b>	ANY ALTERNATE CONTACT <b>Jim Kane</b>	POSITION <b>Site Supervisor</b>	EMPLOYER <b>Shear Diamonds</b>	ALTERNATE CONTACT <b>Jericho Mine Site</b>
			ALTERNATE TELEPHONE <b>778-372-2726</b>	
REPORT LINE USE ONLY				
<b>N</b>	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT
			REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN	
			FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS
LEAD AGENCY				
FIRST SUPPORT AGENCY				
SECOND SUPPORT AGENCY				
THIRD SUPPORT AGENCY				