



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH - DAY - YEAR May 1, 2012	REPORT TIME 6:05pm	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH - DAY - YEAR May 1, 2012	OCCURRENCE TIME 1:15pm		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KTL 311 C015	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-JER1119		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Jericho Mine Site		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 66 MINUTES 01 SECONDS 00		LONGITUDE DEGREES 111 MINUTES 27 SECONDS 00	
F	RESPONSIBLE PARTY OR VESSEL NAME Shear Diamonds	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Suite 220, 6 Adelaide St. Toronto ON M5C 1H6		
G	ANY CONTRACTOR INVOLVED no	CONTRACTOR ADDRESS OR OFFICE LOCATION n/a		
H	PRODUCT SPILLED diesel	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES ~100L	U.N. NUMBER 1202	
	SECOND PRODUCT SPILLED (IF APPLICABLE) none	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES n/a	U.N. NUMBER n/a	
I	SPILL SOURCE fuel hose	SPILL CAUSE person slipped while fueling	AREA OF CONTAMINATION IN SQUARE METRES 4	
J	FACTORS AFFECTING SPILL OR RECOVERY none	DESCRIBE ANY ASSISTANCE REQUIRED n/a	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT n/a	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS -this spill is being reported as required under the conditions in Part H, Section 8(b) of Shear Diamonds Water Board (NWB) Licence 2AM-JER1119 pursuant to the Nunavut waters and Nunavut Surface Rights Tribunal Act, as required by the Government of Nunavut's Environmental Protection Act paragraph 5.1(a) and as required by Environment Canada's Storage Tank Systems For Petroleum Products and Allied Petroleum Products Regulations section 41 pursuant to paragraph 212(1)(a) of the Canadian Environmental Protection Act, 1999 -this incident occurred at 1:15pm, approximately 500m east of Carat Lake -while a fuel truck was being filled with diesel from storage tank EC-00016028, the worker who was standing on top of the truck slipped and almost fell, the fuel hose became disconnected from the truck and sprayed diesel on the worker and the truck -diesel that dripped onto the snow from the truck was immediately shovelled into a nearby berm			
L	REPORTED TO SPILL LINE BY Wes Atchison	POSITION Environmental Tech	EMPLOYER Shear Diamonds	LOCATION CALLING FROM Jericho Mine Site
			TELEPHONE 778-372-2723	
M	ANY ALTERNATE CONTACT Jim Kane	POSITION Site Supervisor	EMPLOYER Shear Diamonds	ALTERNATE CONTACT Jericho Mine Site
			ALTERNATE TELEPHONE 778-372-2726	
REPORT LINE USE ONLY				
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT
			REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN	FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS
LEAD AGENCY				
FIRST SUPPORT AGENCY				
SECOND SUPPORT AGENCY				
THIRD SUPPORT AGENCY				