



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH -- DAY -- YEAR May 5, 2012	REPORT TIME 2:00pm	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH -- DAY -- YEAR May 5, 2012	OCCURRENCE TIME 9:00am		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KTL 311 C015	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-JER1119		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Jericho Mine Site		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 66 MINUTES 01 SECONDS 00		LONGITUDE DEGREES 111 MINUTES 27 SECONDS 00	
F	RESPONSIBLE PARTY OR VESSEL NAME Shear Diamonds	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Suite 220, 6 Adelaide St. E. Toronto ON M5C 1H6		
G	ANY CONTRACTOR INVOLVED no	CONTRACTOR ADDRESS OR OFFICE LOCATION n/a		
H	PRODUCT SPILLED oil	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 15L	U.N. NUMBER 3082	
	SECOND PRODUCT SPILLED (IF APPLICABLE) none	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES n/a	U.N. NUMBER n/a	
I	SPILL SOURCE oil cube	SPILL CAUSE leak	AREA OF CONTAMINATION IN SQUARE METRES 4	
J	FACTORS AFFECTING SPILL OR RECOVERY none	DESCRIBE ANY ASSISTANCE REQUIRED n/a	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT n/a	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS -this spill is being reported as required under the conditions in Part H, Section 8(b) of Shear Diamonds Water Board (NWB) Licence 2AM-JER1119 pursuant to the Nunavut waters and Nunavut Surface Rights Tribunal Act and as required by the Government of Nunavut's Environmental Protection Act paragraph 5.1(a) -this incident was discovered at 9:00am, approximately 700m northwest of Ash Lake -an oil cube located outside of generator #4 of the powerhouse was slowly leaking oil -a tarp that was placed beneath the oil cube during it's initial use stopped most of the spill but there was some oil that seeped through and out of the tarp estimated at 15L -the oil cube was brought inside the truck shop and the oil contaminated snow and ice was removed with a loader and placed in phase II of the fuel tank farm			
L	REPORTED TO SPILL LINE BY Wes Atchison	POSITION Environmental Tech	EMPLOYER Shear Diamonds	LOCATION CALLING FROM Jericho Mine Site
			TELEPHONE 778-372-2723	
M	ANY ALTERNATE CONTACT Chris Morton	POSITION VP Operations	EMPLOYER Shear Diamonds	ALTERNATE CONTACT LOCATION Jericho Mine Site
			ALTERNATE TELEPHONE 778-372-2726	
REPORT LINE USE ONLY				
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT
			REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN	
			FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS
LEAD AGENCY				
FIRST SUPPORT AGENCY				
SECOND SUPPORT AGENCY				
THIRD SUPPORT AGENCY				