



REPORT DATE: MONTH - DAY - YEAR

## **NT-NU SPILL REPORT**

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

REPORT TIME

NT-NU 24-HOUR SPILL REPORT LINE

XORIGINAL SPILL REPORT,

TEL: (867) 920-8130 FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca REPORT LINE USE ONLY

Α	June 5, 2012		7:30	pm	XORIGINAL SPILL REPORT, OR	REPORT NUMBER	
В	OCCURRENCE DATE: MONTH – DAY – YEAR  June 4, 2012		3:05	RENCE TIME	☐ UPDATE # TO THE ORIGINAL SPILL REPO	RT -	
_	LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER (IF APPLICABLE)			
C	KTL 311 CO15			2AM-JER1119			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LO Jericho Mine Site			□ NWT MENUNAVUT □ ADJACENT JURISDICTION OR OCEAN			
Ε	DEGREES WINOTES TO CECONES T		00				
F	RESPONSIBLE PARTY OR VESSE Shear Diamonds		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION  6 Adelaide St. E, Suite 220 Toronto, ON M5C 1H6				
	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION				
G	no	n/a					
Н	PRODUCT SPILLED QUANTITY IN L diesel 4L		N LITRES, K	ILOGRAMS OR CUBIC MET	1202		
	SECOND PRODUCT SPILLED (IF APPLICABLE) QUANTITY IN LITRES, n/a		N LITRES, K	ILOGRAMS OR CUBIC MET	IS OR CUBIC METRES U.N. NUMBER n/a		
	SPILL SOURCE SPILL CAUSE leak		E		AREA OF CONTAMINATIO  6	AREA OF CONTAMINATION IN SQUARE METRES  6	
J	FACTORS AFFECTING SPILL OR none	DESCRIBE ANY ASSIS NONE  LI INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO COM		ANCE REQUIRED	none		
K	Surface Rights Tribunal Act and as required by the Government of Nunavut's Environmental Protection Act paragraph 5.1(a)  -this incident occurred approximately 600m northwest of Ash Lake -while parked behind the process plant it was noticed that the fire truck was leaking fluid -during transport to the truck shop the truck left a small trail of diesel -the truck was immediately brought to the truck shop for inspection and repair -after inspection it was determined that the leaked fluid was diesel -contaminated dirt was shovelled up into a drum and brought to the HWTA						
- Incompany	REPORTED TO SPILL LINE BY  Wes Atchison  POSITION  Environmental Tec				Jericho Mine Site	778-372-2723	
M	Andrew Uyarrai	POSITION Site Services Mngr	She	oyer ear Diamonds	ALTERNATE CONTACT  Jericho Mine Site	ALTERNATE TELEPHONE 778-372-2726	
REPORT LINE USE ONLY							
N	RECEIVED AT SPILL LINE BY POSITION		EMPLOYER L		LOCATION CALLED	OCATION CALLED REPORT LINE NUMBER	
	STATION OPERATOR				YELLOWKNIFE, NT	(867) 920-8130	
LEAD AGENCY DEC DCCG DGNWT DGN DILA DINAC DNEB DTC SIGNIFICANCE DM					MAJOR UNKNOWN FILES	STATUS OPEN CLOSED	
AGENCY CONTACT NAME		DNTACT NAME	co	CONTACT TIME REMARKS			
LEAD AGENCY							
FIRST SUPPORT AGENCY							
SECOND SUPPORT AGENCY							
ТНІ	RD SUPPORT AGENCY						