

D.I.A.N.D
Box 278
Kugluktuk,. Nu. X0B 0E0

Licence Number NWB1JER0410

January, 10 2006

D.I.A.N.D - Nunavut Region
Field Operations- District Manager
P.O Box 100
Iqaluit, NU X0B 0E0

On the 26th of October 2005, I conducted an inspection at the Jericho mine site although the inspection was brief there two minor areas of concern at the refuelling station. There had been a spill of Diesel Fuel of approximately 5 to 10 gallons on the ground beyond the contained bermed area. The other was leaks in the pipes in the pumphouse (at the time of inspection the problem was being looked after). Other than that everything was in compliance.

Sincerely,



George Taptuna
Water Resource Officer
Kitikmeot Region

INTERNAL	
PC	
MA	
FO	
LA	
BS	
ST	
TAI	Copy
TAF	Copy
FC	
ED	Faxed
CH	
BRO	
EXT.	

