




Figure A4
Stability Analysis - Upstream End of Construction - Rotational Slip Surface

FS = 2.00




Figure A5
Stability Analysis - Upstream, Static - Slip Surface Along Liner



FS = 1.36





Figure A6
Stability Analysis - Upstream, Rapid Drawdown - Slip Surface Along Liner




FS = 1.49



Stability Analysis - Upstream, Seismic Analysis -- Slip Surface Along Liner
Figure A7



FS = 1.44



Stability Analysis - Upstream, Static, End of Construction - no coarse tailings
Figure A8






Figure A9
Stability Analysis - Downstream, Static - Rotational Slip Surface