





NAD83
UTMz14
1:1000



LEGEND	
	Ground Surface
	Weathered Bedrock Location
	Bedrock Surface
	Bedrock Surface (Inferred)
	Bedrock Fault
	Bedrock Anomaly

CLIENT		Areva Kiggavik Project 2008–2009 Subsurface GPR Survey			
		Mill Site Profile 2008–2 Proposed Ore Pad Location			
EBA Engineering Consultants Ltd.		Project No. V33101016	DWN RJM	CHKD NSP	REV 0
Office Calgary		DATE Oct. 15, 2009		Figure A13	



LEGEND	
—	Ground Surface
—	Weathered Bedrock Location
—	Bedrock Surface
- - -	Bedrock Surface (Inferred)
—	Bedrock Fault
■	Bedrock Anomaly

CLIENT		Areva Kiggavik Project 2008–2009 Subsurface GPR Survey			
 EBA Engineering Consultants Ltd. 		2008 Mill Site Data Profile 2008–3 Proposed Accommodations Complex Area			
		Project No. V33101016	DWN RJM	CHKD NSP	REV 0
OFFICE Calgary		DATE Oct. 15, 2009		Figure A14	

