



RE: 151201 2AM-LUP1520 October 2015 Annual Geotechnical Inspection Report Lupin Mines Incorporated

1 message

Karyn Lewis <klewis@elginmining.com>

Sun, Jan 31, 2016 at 10:53 PM

To: Eva Paul <Eva.Paul@aadnc-aadnc.gc.ca>

Cc: "Department, Licensing" <licensing@nwb-oen.ca>, "Porter, Ida" <ida.porter@nwb-oen.ca>

Hi Eva and Ida,

Please find attached the following documents:

2AM-LUP1520 2015 Annual Geotechnical Inspection Cover Letter addressing the implementation plan to respond to the Engineer's recommendations as per the 2015 Annual Geotechnical Inspection report submitted to the NWB in 2015.

2AM-LUP1520 2014 Sewage Ponds and Fuel Farm Inspections and 2015 Waste Management Facility Geotechnical Inspection Cover Letter addressing the implementation plan to respond to the Engineer's recommendations as per the 2014 Sewage Pond Dams Geotechnical Inspection, Addendum Memo 2014 Fuel Tank Farm Inspection and the 2015 Waste Management Facility Geotechnical Facility reports submitted to the NWB in 2014 and 2015.

Sincerely,

Karyn Lewis

Lupin Mines Incorporated

778-386-7340

From: Eva Paul [mailto:Eva.Paul@aadnc-aadnc.gc.ca]

Sent: December-07-15 10:15 AM

To: Patrick Downey

Cc: Department, Licensing; Karyn Lewis; Porter, Ida

Subject: Re: 151201 2AM-LUP1520 October 2015 Annual Geotechnical Inspection Report Lupin Mines Incorporated

Thank you for the submission of the Geotechnical Inspections for Lupin Mine.

Please note that as per the licence: *An inspection of the Tailings Containment Area shall be carried out annually during ice free, open-water conditions by a Geotechnical Engineer. The Engineer's report shall be submitted to the Board within sixty (60) days following the inspection, and **shall include a cover letter from the Licensee outlining an implementation plan to respond to the Engineer's recommendations.***

Similarly, as per the requirements of the 2014 Water Licence Inspection: *A geotechnical inspection is to be conducted on all engineered water management structures, including but not limited to: Main and Satellite Tank Farms, Upper and Lower Sewage Lagoon, and waste management areas. The engineer's report is to be submitted to the NWB and to the Inspector by October 31, 2014, **accompanied by a plan and timelines to implement the engineer's recommendations.***

I do not see an accompanying cover letter on file with either of these reports that outlines LMI's plans to implement the engineer's recommendations. Without this component, **LMI is not in compliance with this licence condition.**

Plans with specific timelines to implement the engineer's recommendations are required to be submitted to the NWB and copied to the Inspector by **January 31, 2016**.

Regards,

Eva Paul

Water Resources Officer | Agent des ressources en eau
Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada
Rm 424, 4923-52 St | Pièce 424, 4923-52e Rue
Yellowknife, NWT | Yellowknife, TNO
X1A 2R3
Phone | Tél.: [867-669-2438](tel:867-669-2438)
Cell | Mobile: [867-222-6490](tel:867-222-6490)
Fax | Téléc: [867-669-2702](tel:867-669-2702)
Eva.Paul@aadnc-aadnc.gc.ca

>>> Ida Porter <ida.porter@nwb-oen.ca> 12/1/2015 9:34 AM >>>


Subject: 151201 2AM-LUP1520 October 2015 Annual Geotechnical Inspection Report Lupin Mines Incorporated. Kitikmeot Region

The Nunavut Water Board ("NWB") acknowledges receipt of a submission from Lupin Mines Incorporated entitled October 2015 Annual Geotechnical Inspection Report for Water Licence 2AM-LUP1520 received on December 1, 2015 as a requirement of Part D, Item 6, of the current water licence. This submission has been placed on the NWB public registry and is available from the NWB ftp site.

[ftp://ftp.nwb-oen.ca/1%20PRUC%20PUBLIC%20REGISTRY/2%20MINING%20MILLING/2A/2AM%20-%20Mining/2AM-LUP1520%20LMI/3%20TECH/4%20WASTE%20DISP%20\(D\)%20\(E\)/D%206\(g\)%20Annual%20Geotechnical%20Inspection/2015/](ftp://ftp.nwb-oen.ca/1%20PRUC%20PUBLIC%20REGISTRY/2%20MINING%20MILLING/2A/2AM%20-%20Mining/2AM-LUP1520%20LMI/3%20TECH/4%20WASTE%20DISP%20(D)%20(E)/D%206(g)%20Annual%20Geotechnical%20Inspection/2015/)

This notification is forwarded to interested parties for information.

Regards,



NUNAVUT WATER BOARD - OFFICE DES EAUX DU NUNAVUT
ᓄᓇᓴᓐ ᐱᓕᓕᓄᓐ ᑲᓄᓕᓴᓐ - NUNAVUT IMALIRIYIN KATIMAYINGI

Titigaqavua 119
Uqhuqtina, NU, X0B 1J0

22



2AM-LUP1520 2014 Sewage Ponds and Fuel Tank Farm Inspections and 2015 Waste Management Facility Geotechnical Inspection Cover Letter.pdf
574K