



Lupin Weekly Camp Water and Waste Inspection Form

Date; July 2/16

Time; 0900 am

Inspected by; N. Volny

Description of Facilities; 1300 only

Fresh Water Storage / Pump										Primary Waste Storage					Secondary Waste Storage					
Intake lines in good condition (Y/N)	Discharge lines in good condition (Y/N)	any leaks (Y/N)	worn or damaged water lines (Y/N)	water pump leaks (Y/N)	electrical lines in good condition (Y/N)	electrical lines not in contact with water (Y/N)	water holding tank good condition (Y/N)	water holding tank excess sediment (Y/N)	cover on holding tank (Y/N)	holding tank maintaining proper levels (Y/N)	electrical pump operational	intake lines in good condition (Y/N)	discharge pipe leaking (Y/N)	building heating and lighting in good condition (Y/N)	trailer in good condition including tires (Y/N)	tank in good condition (Y/N)	intake pipe leaking (Y/N)	discharge pipe leaking (Y/N)	lights and heater (if installed) operational (Y/N)	
Y	Y	N	N	N	Y	Y	Y	N	Y	Y	Y	Y	N	N	Y	Y	Y	N	Y	Y
Comments;																				

Upper pond sewage dump point free of spills, debris, and intake open (Y/N); Y

Upper pond sewage line discharge point open, not iced up, and submersed in water (Y/N) Y