

November 10, 2008

Ms. Phyllis Beaulieu  
Manager of Licensing  
Nunavut Water Board  
P.O. Box 119  
GJOA HAVEN NU X0B 1J0  
Canada

Dear Ms. Beaulieu

**Monthly Report for Lupin Mine, October 2008**  
**License 2AM-LUP0008**



This letter provides the monthly report for the Lupin Mine site for October of 2008. The site remains on care and maintenance status. The sewage pond discharge started October 8<sup>th</sup> 2008 at 1:00pm, a syphon was created in 2 8" pipes each having a flow of 250 cubic meters per hour. The flow was measured using a SX30 portable doppler flow meter. The discharge ceased on October 28 2008 at 2:00pm discharging approximately 240,000 cubic meters of water from the lower sewage pond. All chemical analyses are listed on the following page

If you have any questions regarding the status of the Lupin site for September of 2008, please do not hesitate to contact myself at the contact information listed below.

Regards

Aaron MacDonell  
Health Safety and Environment Coordinator

Tel: 807 346 1668  
Fax: 807 345 0284  
Email: [Aaron.MacDonell@zinifex.com](mailto:Aaron.MacDonell@zinifex.com)  
Mobile: (867) 765-8413

Lower Sewage Pond  
SNP-14

Date	Faecal Coliform CFU	BOD5 mg/L	pH	TSS mg/L	As mg/L	Zn mg/L	Cu mg/L	Pb mg/L	Ni mg/L	Cd mg/L	Alk. mg/L	Nitrite mg/L	Nitrate mg/L	Ammonia mg/L	Total Ortho- P	Total P	Hard. (mg/L)
Max Conc.	1000 CFU		6.0- 7.5	35	0.05	0.500	0.200	0.050	0.300								
10/08/08		16	7.10	<3	0.0050	0.003	0.002	<0.005	0.0090	<0.001	28	<0.05	<0.1	<0.05	<0.01	<0.02	112
10/08/08		8	7.50	<3	0.0079	0.010	0.003	0.0008	0.0110	<0.0002	30	<0.05	<0.1	<0.05	0.01	0.04	137