MINERALS AND METALS GROUP

SUITE 200/1159 ALLOY DRIVE THUNDER BAY ON P78 6M8 CANADA TELEPHONE 807 346 1668 FACSIMILE 807 345 0284 MMGROUPLTD.COM

23 August 2009

Ms. Phyllis Beaulieu
Manager of Licensing
Nunavut Water Board
P.O. Box 119
Gjoa Haven Nunavut X0B 1J0

Dear Ms. Beaulieu



A three to five person crew was on site throughout the month of July conducting care and maintenance work at the Lupin site. They were housed in the Guest House on the mine site. Domestic water was provided to the house by hauling water from Contwoyto Lake by truck. Greywater disposal was effected via a leaching pit excavated adjacent to the house. Sanitary waste disposal was effected via a privy with human waste and domestic garbage being incinerated. The consumption of water from Contwoyto Lake was 40,500 Litres (40.5 m³) for domestic use only. The results of the chemical analyses for the raw water sample from Contwoyto Lake at Monitoring Point LUP-01 are attached for reference.

There was no discharge from either the Sewage Lakes System (Monitoring Point LUP-14) or the Tailings Containment Facility Pond 2 (LUP-10). Discharges are expected to commence in August from these facilities.

We trust this provides the information required in the license for the monthly report of activities at Lupin. If you have any questions, please do not hesitate to contact me. I can be reached by phone at 807-346-1692 (direct line) or by e-mail at andrew.mitchell@mmgroupltd.com.

Yours truly

Andrew Mitchell

Development Manager

T 807 346 1692 F 807 345 0284

E andrew.mitchell@mmgroupltd.com

andrew Mitchell

M 807 251 6722

cc Dave Honstein - NWB Dionne Filiatrault - NWB

Martin McFarlane - MMG Resources Inc.

enc Laboratory Test Results - Contwoyto Lake Sample