MINERALS AND METALS GROUP

SUITE 200/1159 ALLOY DRIVE THUNDER BAY ON P78 6M8 CANADA TELEPHONE 807 346 1668 FACSIMILE 807 345 0284 MMGROUPLTD.COM

03 December 2009

Ms. Phyllis Beaulieu Manager of Licensing Nunavut Water Board P.O. Box 119 Gjoa Haven Nunavut, X0B 1J0

Dear Ms. Beaulieu



The Lupin Mine site was closed down for the entire month of November, 2009. There were no personnel on site and as a result, no water taking from Contwoyto Lake at Monitoring Point LUP-1, no discharge from the Tailings Containment Facility, Pond 2 at Monitoring Point LUP-10 and no discharge from the Sewage Lakes Disposal Facility at Monitoring Point LUP-14.

We trust this provides the information required in the license for the monthly report of activities at Lupin. If you have any questions, please do not hesitate to contact me. I can be reached by phone at 807-346-1692 (direct line) or by e-mail at andrew.mitchell@mmgroupltd.com.

Yours truly

Andrew Mitchell

Development Manager

T 807 346 1692 F 807 345 0284

E andrew.mitchell@mmgroupltd.com

andrew Mitchell

M 807 251 6722

cc Dave Honstein - NWB Dionne Filiatrault – NWB Melissa Joy - INAC

Martin McFarlane - MMG Resources Inc.

Encl. Summary of Monitoring Test Results-Surveillance Network Program