

Lupin Mines Incorporated
(a subsidiary of Elgin Mining Inc.)

08 June 2013

Ms. Phyllis Beaulieu
Manager of Licensing
Nunavut Water Board
P.O. Box 119
Gjoa Haven, NU
X0B 1J0

Dear Ms. Beaulieu

RE: Monthly Report for May 2013
Lupin Mine, Nunavut, License Number 2AM-LUP0914

Activities on site during the month of May involved the collection of water samples from the various tank farm berms in preparation for dewatering, and a routine inspection of the facility, including freshet monitoring on May 27, 2013. The facilities were found to be in good condition with no signs of leaks in any of the fuel tanks and associated piping. No erosion as a result of runoff was observed around the general site area. The Tailings Containment area could not be inspected, as there was too much snow in places along the access road to gain access at this time. An aerial observation did not reveal any anomalies in the area. Another site inspection will be conducted in June.

If you have any questions regarding the above, please do not hesitate to contact me.

Sincerely,
Lupin Mines Incorporated.


Wayne Osborne
Project Manager

2AM-LUP0914

060813-2AM-LUP0914-MONTHLYREPORTMAY2013

This file is produced electronically with 1 page

Lupin Mines Incorporated
#201-750 West Pender St.
Vancouver, BC Canada V6C 2T8
Phone: +1 (604) 682.3366 Fax: +1 (604) 682.3363