

Lupin Mines Incorporated
(a subsidiary of Elgin Mining Inc.)

5 November 2013

Ms. Phyllis Beaulieu
Manager of Licensing
Nunavut Water Board
P.O. Box 119
Gjoa Haven, NU
X0B 1J0

Dear Ms. Beaulieu

RE: Monthly Report for October 2013
Lupin Mine, Nunavut, License Number 2AM-LUP0914

Activities on site during the month of October involved care and maintenance only. There were no people staying on site throughout the month.

A regular site inspection was completed on October 8th by Arlene Laudrum of SRK and Mathieu Beaudoin of Discovery Mining Services. The tailings containment area, fuel storage areas, and building s were inspected. No significant issues were observed.

There was no domestic water used, no sewage produced, and no domestic waste generated during the month.

If you have any questions regarding the above, please do not hesitate to contact me.

Sincerely,
Lupin Mines Incorporated.

George Friesen
Manager of Technical Services

CC: Patrick Downey, CEO of Elgin Mining Inc.