

## **Appendix F3**

---


### **Aboveground Fuel Line Inspection Reports**

---



AGNICO EAGLE

# Work Order



Unit Number 6163BLD01

Order Number 1283030

**Equipment Description:**  
POWERPLANT BUILDING

**Description:** WEEKLY INSP. FUEL LINE  
PREVENTIVE MAINTENANCE

**Location:**

**Order Type :** WM  
**Type:** 6 PREVENTIVE MAINTENANCE WO  
**Priority:** 2 UNPLANNED  
**Status:** 70 In Execution

**Estimates:**

**Est. Hours:** 6.00  
**Estimated Downtime Hours:** 6.00

**Parent W.O. No:** 01283030  
**Business Unit:** 6134615  
**Subsidiary:**

**People :**

**Crew:** 15037 Team Surface Maintenance Meado  
**Lead Craft:** Plumber  
**Supervisor:**  
**Assigned To:** 108992 Little, Rob  
**Requester:**  
**Originator:** 66211 Ferland, Claude  
**Inventory Item Number:** 210202

**Dates :**

**Order Date:** 2015-10-29  
**Requested Finish Date:**  
**Planned Start Date:** 2015-11-03  
**Planned Finish Date:** 2015-11-03

**Actual Start Date :**

**Start time :**

Work to be done

FILL ATTACHMENT

Work Done

DONE

**Actual Finish Date**

**End Time**

6/11/15

**Employee**

Rene Buhara

**Downtime**

4 hrs

CLOSE

Rene Bertrand



## AGNICO EAGLE

MEADOWBANK

### Weekly line Inspection

WO :

Date :

Unit #:6163BLD01



Legend:

|         |   |
|---------|---|
| Confirm | ✓ |
|---------|---|

Non-confirm X

If non-confirm, please write details.

[illegible]

**AGNICO EAGLE**  
MEADOWBANK

WO: 129 4359

Date : 27-11-2015

Unit #:6163BLD01

**Legend:**

|         |   |
|---------|---|
| Confirm | ✓ |
|---------|---|

|               |
|---------------|
| Non-confirm X |
|---------------|

If non-confirm, please write details.

[illegible]

AGNICO EAGLE

MEADOWBLANK

## Fuel Line to Power Plant

## Weekly line Inspection

WO: 1299581

Date: 05-12-2015

Unit #: 6163BLD01



Legend:

Confirm ☒

Non-confirm X

If non-confirm, please write details.

No.

Tasks

Maintenance  
type

Monthly

Remarks

- |    |  |                                     |  |
|----|--|-------------------------------------|--|
| 1  | WALK ALL THE LINE TO VERIFY ANY ANORMALITY AND LEAK                  | <input checked="" type="checkbox"/> |  |
| 4  | VERIFY THE GASKET FOR ANY LEAK                                       | <input checked="" type="checkbox"/> |  |
| 5  | VERIFY INSIDE THE 5 CULVERT FOR ANY LEAK OR DEFLEXION OF THE CULVERT | <input checked="" type="checkbox"/> |  |
| 6  | CHECK IF ALL THE SUPPORT ARE OK ON THE LEACH PAD AND ON THE GROUND   | <input checked="" type="checkbox"/> |  |
| 7  | CHECK IF THE SIGN ARE ALREADY IN PLACE                               | <input checked="" type="checkbox"/> |  |
| 7  |  |                                     |  |
| 8  |  |                                     |  |
| 9  |  |                                     |  |
| 10 |  |                                     |  |
| 11 |  |                                     |  |
| 12 |  |                                     |  |
| 13 |  |                                     |  |
| 14 |  |                                     |  |
| 15 |  |                                     |  |
| 16 |  |                                     |  |

DATE:

5-2015-12

INSPECTOR:

Rene Bertrand

INSPECTOR:

Comments:

WE DON'T SEE ANY LEAK.  
FOR ALL THE FUEL LINE 3"

Rene Bertrand

**Comments:**